

CELANESE CHEMICAL COMPANY, INC.
TECHNICAL CENTER
Corpus Christi, Texas

PLAINTIFF'S
EXHIBIT
CEL-588

To: W. S. Roussel - CCCTC
From: D. O. Anderson DOA-264-84 February 21, 1984

Asbestos Disposal - Warehouse

The following information is provided to assist you in asbestos disposal:

- 1) Obtain approximately 3 or 4 open top barrels and move to warehouse. Barrels are used for lab hazardous waste disposal and are available through the pilot plant.
- 2) Obtain plastic barrel liners for asbestos disposal and install in barrels. The liners are in the safety cabinet/warehouse.
- 3) Locate asbestos materials and place into lined barrels. Note: proper protective equipment (coveralls, gloves and respirators)* should be worn.
- 4) Seal plastic liners.
- 5) Place top on barrels and seal.
- 6) Make stencil and label barrels to read Caution: ASBESTOS
- 7) Transport barrels to hazardous waste storage facility, located west of B-149.
- 8) When hazardous wastes are removed from premises, these barrels will be included for proper off-site disposal.

When items 1 and 2 are completed, I will be glad to supervise, assist or instruct personnel if requested.


D. O. Anderson

lnj

008326

*Impervious Tyvek-type coveralls available through maintenance; gloves (rubber) available in warehouse; respirators available from SH&E (3M-#8710).

128549 FEB 29 84