

ASBESTOS HANDLING AND DISPOSAL

Page 6 of 10

July 25, 1985

NOTES AND REFERENCES

2. The Material Recovery Center will not accept insulated hardware unless it is known to be free of asbestos and is so labeled.

3. Asbestos waste shall be collected and disposed of in sealed, impermeable bags or containers.
CTI-87-03-110.

Caution labels shall be attached conforming to Figure 2.

some instances to wrap and tape the entire wagon rather than the individual pieces.

- o Should the MRC personnel discover insulated hardware not labeled, the following action should be taken:

- 1) If sender is known, they will be requested to remove it for stripping in accordance with Paragraph C.

- 2) If sender is not known, then:

- (a) Maintenance Services will treat it as though it were asbestos and have it removed to #311 Tank Farm for stripping.

- o Asbestos contaminated clothing and throw away respirators shall be handled in sealed labeled bags with instructions for proper handling.

DUP 0908712