Out=Remove from Stores stock

TABLE

ASBESTOS RELATED PROBLEMS, COMMENTS, AND SUGGESTED SOLUTIONS

ITEM	DESCRIPTION	COMMENTS	SUGGESTED SOLUTIONS
a.	Asphalt Mastic	No problem unless sprayed	Do not spray
b.	Braided Packing	Contained, considered safe to handle	Personnel monitoring to verify claim
c.	Asbestos Gloves	Probable source of exposure	Personnel monitoring. Look for substitute
d.	Heat Suits	Same as 1.c.	Look to aluminized "Nomex" as substitute
e.	Hot Pads	Same as 1.c.	Same as 1.c.
f.	Insulation	Separate listing	See Item 2
g	Molded packing	Contained, no problem	None required
h.	Sheet gasketing	Contained, no problem	None required
a.	Calcium Silicate	Probable source of high exposure	Personnel monitoring to verify claim. Look for substitute material.
b.	Inhibited Calcium Silicate	Same as 2.a.	Same as 2.a.
c.	Kaylo 20	Same as 2.a.	Same as 2.a.
d.	Asbestos Board	Problem when sawed	Same as 2.a.
e.	Asbestos Roofing Felt	Contained, no problem	None required
f.	Fibrated asphalt Emulsion	No problem unless sprayed	Do not spray
g.	Fibrated asphalt Cut-back	Same as 2.f.	Same as 2.f.
	Asbestos Cloth (listing tape)	Possible source of high exposure	Personnel monitoring to verify claim. Evaluate J-M Thermo-chem tape as substitute.

135

DUP 0900982

4-B-71

121311