

VCM FLASHER ANALYSIS

DATE: 12/16/25

RT STDS A: 3.39, 3.40, 3.41, 3.43, 3.45
B: 3.25, 3.27, 3.29

BLDG	NAME	DATE	TUBE NO	RESP	FLOW RATE	TIME	RET. TIME A	RET. TIME B	AREA or PEAK HT	VCM RESULT	Notes
1		12/13	85	2	45.4	360	3.40		114x2	0.15	
1		12/13	57	2	38.5	360		3.22	23649	1.23	
1		12/13	36	2	41.4	360	3.42		92x16 357045	1.23	12
1		12/13	98	2	35.6	360		3.20	19634	0.94	
1		12/13	32	2	42.3	360	3.43		34217	0.13	
1		12/13	6	2	45.2	360		3.20	3572	0.21	
1/4/15		12/12	116	0	50.1	360	3.44		299900	1.45↓	
15		12/12	53	2	53.6	360		3.26	44825	3.26	
"		"	93	"	"	"	3.41		36x32	0.95	
15		12/12	110	2	42.1	360		3.24	24516	1.40	
"		"	19	"	"	"	3.40		193485	0.78	
15		12/13	K	2	51.25	360		3.29	20056	1.39	
15		12/13	107	2	33.3	360	3.38		44x4	0.08	
15		12/13	3	2	40.9	360		3.27	15926	0.88	
17		12/12	49	0	54.1	360	3.46		3409	0.01	
108		12/14	102	-	43.8	365		3.20	6167	0.35	
108		12/14	105	0	43.1	365	3.40		30x8	0.15	
111		12/12	2	0	43.6	360		3.32	8964	0.52	
111		12/12	117	1		10	100		PUMP FAILURE		
111		12/12	18	0	53.4	360		3.24	5926	0.42	