PLAINTIFF'S EXHIBIT

DOW-769

I.H. PLANS FOR 1990

Treat the remaining transformers in the block which contain levels of PCBs.

Conduct I.H. monitoring on the block sampling devices.

Update the written block respirator program.

Continue to vacuum the asbestos gasket storage area.

Work with LAD industrial hygiene department in gathering more data on NORM.

ST0075099