

Ethanolamines/Glycol Ethers

In Plant Training (IPT)

Section Number :8
Issue Number :1.2
Origination Date :06-14-91 Author: Mike Viator
Revision Date :12-12-94
Section Test :8

=====

Lab Familiarization Area Hazards

Answers:

- 1. State the minimum safety equipment for the lab.**
Safety glasses are a basic requirement. Rubber gloves are also required for some jobs along with monogoggles.
- 2. Physically locate the lab safety shower(s) and fire extinguisher(s).**
- 3. State the hazards associated with the chemical used to dry glassware in the lab. State the name of the chemical.**
The chemical used for drying glassware is methanol and the hazards associated with it are as follows: TLV is 200 ppm. Methanol may be fatal or cause blindness if swallowed. It is also flammable.
- 4. State what information can be obtained to inform a person of the chemicals used in the lab and in block 55.**
The hazardous material manuals are located in the lab and contain all important information about the chemicals in the block.

Revisions:

Revision No. 1	07-21-93	Yearly Review
----------------	----------	---------------

Revision No. 2	12-12-94	Yearly Review
----------------	----------	---------------
