ALM#3 C.V. 106

MAKING INSTRUCTIONS: BATCH UNIT

D.V.

CG 46 CODE Y1-808-D PKG. ____

→ 6/25/82 F2L20

EST. WGT. 0 LBS.

STD. HRS. ____ TIME 3 P. M.

PROCESSES		APPROVED BY
( )	( )	
( )	( )	
( )	( )	
( )	( )	
TYPED BY		

46 YC-40-A 93 J1063-1 207S#

46 YC-40-A 98 J1063-1 116#

(Reg. No. 10864)

TOTAL WT ~~2114#~~ 2114#

3 P.M. NON-BLEEDING

SHIPMENT		NAME: DALAMAR Yellow	USE LBS.	N CODE	ACCT. LBS.
PREP 1	1	OBTAIN YC40-A LISTED ABOVE 12 DRUMS		YC40-A	2191
ALM 2	2	PLUG ALM 1 OUTLET & RUN IN 1000# WATER			
	3	START AGITATOR, DUMP & RINSE IN YC- -A LOT J1063 NO DRS 3			
	4	STIR 5-10 MINUTES ADDING WATER AND/OR YC-40-A TO SMOOTH SLURRY			
SV 3	5	PUMP ALM WITHOUT AGITATION INTO V-106			
	6	REPEAT STEPS 2 THRU 5 FOR AS MANY SET-UP AS NECESSARY SET-UP 3 4 NO DRUMS 1			
SV 4	7	WASH ALM & PUMP INTO SV			
	8	ADJ TO 60" (60006) AT 120-130°F			

START 6:30 P.M. FIN 10:10 P.M. OPTR 381

JUN 25 1982

N38149