

1 —

FC 8.1.1

A

To: Distribution

From: Chip Madigan
Date: September 10, 1987

VISTA

Interoffice
Communication

Subject: VCM Leak Detection Survey

Attached are the results of the completed 1987 Comprehensive VCM Leak Detection Survey. A total of forty-one (41) leaks were detected and repaired. Every connection, flange, valve, etc., in VCM service was checked with a portable hydrocarbon detector (HNU). The points with readings above 50 ppm, with the probe as close to the equipment as possible, were considered leaks and were noted. A list of all VCM leaks is attached.

If there are any questions or comments, please contact me.

Chip Madigan

Chip Madigan
Co-Op Process Engineer

nrs

cc: JF, JWW, PJK, VEM, DFJ, RAF, MLN, TFL, SCH