

**Chlorinated Methanes
Products Plant
Consolidated Audit**

Type

REACTIVE CHEMICAL

Area

General

Recommendations:

1. Due to reactivity concerns, titanium parts are not allowed in the Methanes block. The current trend toward centralization of maintenance and spare parts increases the risk of inadvertently importing titanium into the block. It may be beneficial to communicate this issue and associated hazards with the appropriate personnel at Solvents/EDC 1 and central warehouse.

Description: Titanium Parts

Action

Again, Methanes does not allow titanium parts in the block and the equipment replacement spare parts have been scrutinized to ensure that no titanium is specified. This policy has been well communicated to maintenance personnel in the block. The Centralized Maintenance Organization must address this and similar issues from a safety training perspective. We will work with the CHM group to develop and execute this training.

Response

Scope

Change:

Responsibility Bruce Miles

Checkpoint Date: 1/93

Timing: 02/93

Status: Complete