BULLETIN NO. PCE-019 DATE 10/81

4.2L/5.OL ENGINES OIL LEAKS

FORD LINCOLN-MERCURY 1980-81
4.2L/5 .OL ENGINES OIL LEAKS

1980-81 cars and light trucks with the 4.2 liter or 5.0 liter engines may have seepage or leaks at the oil pan bolts.

These bolt holes are threaded through the crankcase. To prevent the seepage/leakage problem, apply a small amount of Victor Odd Job to the oil pan bolts before installation. Be sure the oil pan is not damaged and the mating surfaces are very clean. Of course, our cork/rubber oil pan gasket, #0530531 is recommended.

CAUTION: Do not apply Odd Job on any bolt that is not drilled all the way through.