

RE: ZITIS, FRIEDMAN
GM'S ANS TO ROGS

10. ANSWER:

- (a) Brake assemblies (with linings) sold under the names "GM Parts" and "Delco". Brake linings (sold separately or as part of brake assemblies) sold under the names "GM Parts", "Delco", "DM-5470", "DM-5490", "DM-8010", and "DM-8011". Linings called "Inlite". Brake shoes known as "5K04" and "Gold Bond 5K04".
- (b) Throughout the period 1950-1975.
- (c) Throughout the period 1950-1975, GM manufactured brake linings which contained approximately 50% (by weight) chrysotile ("white") asbestos.
- (d) See attached copies of the following documents:
 - (1) "Genuine GM Replacement Brakes";
 - (2) "Moraine Brake Linings"; and
 - (3) Copies of pages 454-456, 457-458, 468-469, and 469-474 from AC-Delco publication No. 17A100-2 setting forth the following information: AC-Delco Part No., Type Brake Size and FMSI No., FMSI No. to AC-Delco Part No., illustrated section showing primary and secondary shoe and lining, and information pertaining to disc brake pad assemblies for various applications.
- (e) Since August 1, 1975 General Motors has attached an asbestos caution label (No. 1420) to all brake shoes, brake linings and transmission clutch plates within its distribution system. This requirement has been continued since August 1, 1975 for all new parts released in these categories. The warning is printed on a pressure sensitive label in black lettering on bright yellow coated stock. The warning contains the following information:

CAUTION: CONTAINS ASBESTOS FIBERS.
AVOID CREATING DUST. BREATHING
ASBESTOS DUST MAY CAUSE SERIOUS
BODILY HARM.

8002 0533