

Accident Prevention Manual

FOR INDUSTRIAL OPERATIONS

3d EDITION

1955

NATIONAL SAFETY COUNCIL

CHICAGO • U. S. A.

PLAINTIFF'S EXHIBIT

NSC-58

Section 1: E. W. Andrews. Section 2: Dan Adair. Section 3: Leonard C. Smith. Section 4: Franklin G. Pater. Section 5: Howard C. Klopp. Section 6: Glenn F. Griffin. Section 7: James D. Saul. Section 8: Paul Jones. Section 9: H. Gene Miller; *revised by author*. Section 10: H. Gene Miller; *revised by author*. Section 11: Robert D. Gidel.

Section 12: Roy G. Benson; *revised by author*. Section 13: G. G. Grieve; *revised by author*. Section 14: Robert L. Moore and George MacDonald; *Robert L. Moore*. Section 15: William N. Davis; *J. C. Kato*. Section 16: William N. Davis; *Wendell R. Blair*. Section 17: William N. Davis; *J. C. Kato*. Section 18: Lester W. Dutton; *revised by author*. Section 19: W. E. Rossnagel and Lester W. Dutton. Section 20: Lester W. Dutton. Section 21: Lester W. Dutton; *revised by author*. Section 22: Lester W. Dutton; *G. G. Grieve*.

Section 23: Arthur S. Kelly; *revised by author*. Section 24: Arthur S. Kelly; *revised by author*. Section 25: Arthur S. Kelly; *revised by author*. Section 26: Arthur S. Kelly; *Dan Adair*. Section 27: Arthur S. Kelly; *revised by author*. Section 28: William G. Hazard. Section 29: Floyd E. Frazier and William N. Davis; *A. F. Tyra and associates and Wendell R. Blair*. Section 30: A. M. Baltzer; *George MacDonald*. Section 31: George MacDonald; *revised by author*. Section 32: Roy G. Benson; *Howard H. Warzyn*. Section 33: Roy G. Benson; *Howard H. Warzyn*. Section 34: Roy G. Benson; *Howard H. Warzyn*.

Section 35: Howard H. Warzyn. Section 36: Floyd A. Van Atta; *revised by author*. Section 37: Stewart A. Washburn. Section 38: Clark D. Bridges. Section 39: Floyd A. Van Atta. Section 40: Floyd A. Van Atta; *revised by author*. Section 41: Floyd A. Van Atta; *revised by author*. Section 42: C. W. Imhoff and G. G. Grieve. Section 43: compiled by Leonard C. Smith.

Robert J. Sullivan, Senior Editor, Industrial Department, directed the technical assembly, editing, and production of this THIRD EDITION. Assisting were Editors Eilene W. Perry, James D. Saul, and Will A. Whitney. Neil T. Kinney handled art production. Mildred M. Grant of the Council Library prepared the alphabetical Index.

CONTENTS

	SECTION
Basics of Safety.....	1
Safety Organization	2
Safety Committees	3
Removing the Hazard from the Job.....	4
Human Behavior and Industrial Safety.....	5
Safety Education.....	6
Maintaining Employee Interest in Safety.....	7
Public Relations and Publicity for Safety.....	8
Accident Records and Injury Rates.....	9
Accident Investigation, Analysis, and Costs.....	10
Workmen's Compensation Insurance.....	11
Sources of Help for the Safety Man.....	12
Industrial Buildings and Plant Layout.....	13
Plant Construction and Maintenance.....	14
Boilers	15
Pressure Vessels	16
Refrigeration Equipment.....	17
Handling and Storage of Materials.....	18
Hoisting Apparatus and Conveyors.....	19
Elevators and Plant Railroads.....	20
Power Trucks and Tractors.....	21
Ropes, Chains, and Slings.....	22
Principles of Guarding and Transmission Guards.....	23
Metal Forming and Shearing.....	24
Machine Tools.....	25
Woodworking Machinery	26
Guarding Equipment in Selected Industries.....	27
Local Exhaust Systems and Ventilating.....	28
Welding and Cutting.....	29
Hand and Portable Power Tools.....	30
Electrical Hazards.....	31
Flammable Liquids.....	32
Fire Prevention.....	33
Fire Extinguishment and Control.....	34
Emergency Action Plans.....	35
Personal Protective Equipment.....	36
Industrial Sanitation and Personnel Facilities.....	37
Medical, Nursing, and First-Aid Services in Industry.....	38
Industrial Hygiene	39
Industrial Poisons.....	40
Table of Chemical Hazards.....	41
Motorized Equipment	42
Safety Engineering Tables.....	43

urine. The kidneys may then become too clogged to operate at all.

The possibility of arsine formation should always be considered when there is hydrogen formation around the active metals or around ores of the heavy metals, since arsenic is widely distributed in small amounts and only a trace of it is required to produce enough arsine to be troublesome.

One of the more common sources of arsine incidents in recent years has been the handling of dross from the aluminum refining of metals.* Probably the most significant observation about these cases, aside from the fact that the moisture in the atmosphere is enough to form arsine, is the fact that the people involved in them have not been aware of the garlic-like odor which is supposed to be a warning of the presence of arsine.

The extremely high acute toxicity is reflected in the threshold concentration of 0.05 ppm. Arsine, in very small amounts, is also capable of producing a chronic type of poisoning, but it is more typically a source of acute episodes.

Asbestos is a hydrated magnesium silicate found in the minerals chrysotile, amianthus, actinolite and tremolite. Practically all the commercial asbestos is either chrysotile or amianthus, and about 90 per cent of that used in this country is chrysotile. It is used almost exclusively for heat insulation or for textiles which must resist high temperature, such as heat-resistant clothing and brake linings.

Inhalation of excessive quantities of asbestos fiber can produce a fibrosis in the lungs similar to that found in silicosis but somewhat milder and usually not so rapidly progressive. Like silicosis, the condition develops slowly and advances slowly and is equally resistant to treatment.

Prevention is essentially dust control. A maximum dust concentration of 5 million particles per cubic foot has been suggested, precisely as for pure free silica.

Barium, in the form of its soluble salts, is both toxic on ingestion and inhalation and highly caustic when applied to the skin. The carbonate and sulfide are sufficiently

soluble to be toxic, although not very caustic. The sulfate, which is used as a contrast medium in X-ray work, is too insoluble to show any toxicity, and soluble sulfates are specific antidotes for ingested barium salts.

Since these salts produce violent stimulation of all muscle, upon ingestion they produce severe disturbances of the digestive system. After absorption, the barium salts produce an increase of blood pressure by constriction of the arterial muscle, a slow heart beat by an action similar to that of digitalis on the heart, and first excitation and then paralysis of the central nervous system. In spite of the high inherent toxicity, there are few cases of industrial poisoning with barium.

Barium is a heavy metal, and the dust of the insoluble salts will collect in the lungs and give rise to the condition known as baritosis. Its nodular appearance on X-ray film may be mistaken for that of silicosis. Men showing the sign of baritosis are apparently not disabled or inconvenienced in any way.

Benzene is a colorless, flammable, volatile liquid with a rather pleasant aromatic odor. Its fire hazard is between that of ethyl alcohol and that of ether. *The greatest hazard is that of chronic poisoning by inhalation of comparatively small amounts over a long period of time. It is one of the two or three most dangerous organic solvents in commercial use.*

The action is primarily on the blood-forming organs, producing severe anemia, bleeding under the skin, and great reduction in the ability of the blood to clot.

The extent of chronic exposure to benzene may be determined qualitatively by measurement of the ratio of organic to inorganic sulfates in the urine. The most convenient measurement of damage is given by a blood count.

People who may be exposed to benzene vapor should have blood counts at regular intervals. Consistent change in the blood count should be closely investigated. Particularly significant changes are diminution in the total numbers of red cells, platelets, or white cells.

Headaches, dizziness, fatigue, loss of appetite, irritability, nervousness, nosebleed, and other signs of abnormalities of the blood may or may not be present in chronic poisoning.

*"Arsine Poisoning, Epidemiologic Studies of an Outbreak Following Exposure to Gases from Metallic Dross," Louis W. Spoljar, R. N. Harger, *Archives of Industrial Hygiene and Occupational Medicine*, 8:419-436 (1950).

TABLE OF CHEMICAL HAZARDS—Continued

Substance	Flash point ° F.	Explosive limits % by volume		Auto-ignition temperature ° F.	Maximum acceptable concentration for 8-hr. exposure	Usual mode of entrance to body	Signs and symptoms of poisoning
		Lower	Upper				
ammonia	gas	16	25	1204	100 p.p.m. ¹	inhalation	Severe irritation of eyes and respiratory passages, cough, caustic action on skin.
amyl acetate-n	77	1.1	...	750	400 p.p.m. ^{1, 2} 200 p.p.m. ^{3a}	inhalation	Irritation of eyes and respiratory tract, headache and dizziness, cough, nausea.
amyl alcohol-iso	109	1.2	...	650	100 p.p.m. ^{3a}	inhalation	Same as amyl acetate.
amyl alcohol-n	100	1.2	...	700	100 p.p.m. ²	inhalation	Same as amyl acetate.
aniline	168	...	...	1000	5 to 7 p.p.m. ⁵	absorption through skin, inhalation, or ingestion	<i>Acute:</i> weakness, dizziness, blueness of lips, fainting, possible death. <i>Chronic:</i> disturbances of equilibrium, nausea, vomiting, diarrhea, eczema, sleepiness, and irritability.
antimony (salts)	metal and sulfides flammable				0.5 mg/cu.m. ^{3a}	inhalation of dust, ingestion	<i>Acute:</i> vomiting, colic, diarrhea, irritation of mouth and throat. <i>Chronic:</i> indigestion, loss of weight and appetite, sometimes severe dermatitis.
arsenic	...	...	...	...	0.15 mg/cu.m. ⁴ 0.5 mg/cu.m. ^{3a}	inhalation of dust, ingestion and direct action on skin and mucous membrane	Irritation of skin, loss of hair and nails, perforation of nasal septum, hoarse voice, cough, neuralgic pains, diarrhea.
arsine	...	...	...	...	1 p.p.m. ⁶ 0.05 p.p.m. ^{3a}	inhalation	Headache, nausea, vomiting, chills and shivering, jaundice, dark or bloody urine.
asbestos	non-flammable				5 m.p.p.c.f. ⁵	inhalation	<i>Chronic:</i> shortness of breath, asbestos corns.

TABLE 43-P. A GUIDE TO VENTILATION RATES FOR TYPICAL INDUSTRIAL EQUIPMENT
State or Local Regulations Should Be Consulted and Followed Where Higher Ventilation Rates Are Specified

Operation	Ventilation		Usual Transport Velocity (FPM)	Remarks and References
	Type of Hood	Air Flow		
Abrasive blast rooms (sand, grit or shot)	Tight enclosure with air inlets (usually in roof)	60-100 fpm downdraft (long rooms of tunnel proportions 100 fpm cross-draft)	3500	Ref. 8. Many codes specify minimum downdraft of 80 fpm
Abrasive blast cabinets	Tight enclosure with access openings	20 air changes per minute but not less than 500 fpm through all openings	3500	Ref. 14
Asbestos Carding Spool winding	Enclosure Local Hoods	800 cfm per machine 50 cfm per spool	3000 3000	Ref. 2, 15, 16. See references for details and other operations
Bagging Open Bag Top	Booth or enclosure (provide spillage hopper)	Paper bags—100 cfm per sq. ft. open area	3500	Ref. 17
		Cloth bags—200 cfm per sq. ft. open area	3500	
Barrels — Drums (filling or removing material by scoop)	Local Hood	100 cfm/sq. ft. of container cross section	3500	Ref. 13, 18. Hood with 1-in. slot extending 120 to 180 deg container. Does not confine spillage. Confine spillage—also recommended for container upsetting
	Booth	100 fpm at face	3500	
Belt conveyors	Hood at transfer point	Belt speeds less than 200 fpm—350 cfm per foot of belt width, but not less than 150 fpm through open area. Belt speeds over 200 fpm—500 cfm per foot of belt width but not less than 200 fpm through open area	3500	Ref. 17, 19
Bins (closed top)	Connect to bin top away from feed point	150-200 fpm through open area at feed points	3500	Ref. 18, 19
Bucket elevators	Tight casing required	10 cfm per sq. ft. of elevator casing cross-section	3500	Ref. 18

TABLE 43-P. A GUIDE TO VENTILATION RATES FOR TYPICAL INDUSTRIAL EQUIPMENT

REFERENCES FOR TABLE 43-P

- ¹The Determination and Control of Industrial Dust, by J. J. Bloomfield and J. M. DallaValle (*Bulletin 217, U. S. Public Health Service*, 1935).
- ²Exhaust Hoods, by J. M. DallaValle (Industrial Press, New York, 1952).
- ³Design of Exhaust Hoods for Dust Control Systems, by T. Hatch (*Journal of Industrial Hygiene and Toxicology*, Vol. 18, 1936, p. 595).
- ⁴Air Dilution in Industrial Ventilation, by W. C. L. Hemeon (*Heating and Ventilating*, February 1941).
- ⁵Practical Application of Industrial Exhaust Ventilation for the Control of Occupation Exposures, by B. F. Postman (*American Journal of Public Health*, Vol. 30, 1940, p. 149).
- ⁶Principles of Industrial, Process Ventilation, by W. N. Witheridge (*University of Michigan Inservice Training Course*, October, 1945).
- ⁷Industrial Dusts, by Philip Drinker and Theodore Hatch (McGraw-Hill Book Co., New York, 1936).
- ⁸Design of Industrial Exhaust Systems, by J. L. Alden (Industrial Press, New York, 1948).
- ⁹Ventilation, by W. N. Witheridge (*Industrial Hygiene and Toxicology*, Vol. I, Chap. 10, Edited by F. A. Patty. Interscience Publishers, New York, 1948).
- ¹⁰Transport Velocities for Industrial Dusts, by A. C. Stern et al (*American Industrial Hygiene Association Quarterly*, December 1948).
- ¹¹Industrial Health Engineering, by A. D. Brandt (John Wiley and Sons, New York, 1947).
- ¹²Velocity Characteristics of Narrow Exhaust Slots, by Leslie Silverman (*Journal of Industrial Hygiene and Toxicology*, November 1942, p. 267).
- ¹³Industrial Ventilation Manual, (American Conference of Governmental Industrial Hygienists, 1952 Edition).
- ¹⁴Code of Recommended Good Practice for Metal Cleaning Sanitation (American Foundrymen's Association).
- ¹⁵A Study of Asbestos in the Asbestos Textile Industry, by W. C. Dressen et al (*U. S. Public Health Service, Bulletin 241* 1938).
- ¹⁶A Study of Dust Control Methods in an Asbestos Fabricating Plant, by R. T. Page and J. J. Bloomfield (*U. S. Public Health Reports*, Reprint No. 1883, Nov. 26, 1937).
- ¹⁷Rules Relating to the Control of Silica Dusts in Stone Crushing Operations (*New York State Department of Labor*, Industrial Code Rule No. 34, July, 1942).
- ¹⁸Design of Exhaust Systems, by J. M. Kane (*Heating and Ventilating*, November 1945, p. 68).
- ¹⁹Foundry Ventilation, by J. M. Kane (*The Foundry*, February and March, 1946).
- ²⁰Pottery Dusts: Their Collection and Removal, by W. M. Oddie (*Pottery Gazette*, Vol. 53, 1928, p. 1280).
- ²¹Scrapbook of Exhaust Hoods, by J. M. Kane (*Heating and Ventilating*. Portable Grinding—July 1950; Grinding, Polishing, Buffing—August 1950; Foundry Shakeout—November 1950; Melting Furnaces—February 1951; Pottery—March 1951; Mixers—April 1951; and Woodworking—June 1951).
- ²²Design of Exhaust Ventilation for Solid Material Handling, by R. T. Pring et al (*Industrial and Engineering Chemistry*, November 1949).
- ²³Hartzell Blowers: Engineering Data & Installation (Hartzell Propeller Fan Company, Bulletin 1001).
- ²⁴The Application of Local Exhaust Ventilation to Electric Melting Furnaces, by J. M. Kane (Transactions, American Foundrymen's Association, Vol. 52, 1945, p. 1351).
- ²⁵Control of Silicosis Hazard in the Hard Rock Industries. II. An Investigation of the Kelley Dust Trap for Use with Pneumatic Rock Drills of the Jackhammer Type, by T. Hatch et al (*Journal of Industrial Hygiene*, February 1932, p. 69).
- ²⁶Modified Design of Hay Dust Trap, by P. S. Hay (*Journal of Industrial Hygiene*, January 1930, p. 28).
- ²⁷American Standard for Grinding, Polishing and Buffing Equipment Sanitation (*American Standards Association*, Z 43-1941).
- ²⁸Swing Frame Grinder Dust Control, by J. M. Kane (*The Foundry*, August 1944).
- ²⁹What We Make (B. F. Sturtevant Co., Catalog No. 500).
- ³⁰Ventilation of Motion Picture Booths, by P. Drinker and J. R. Snell (*Journal of Industrial Hygiene and Toxicology*, April 1938, p. 321).
- ³¹How to Justify an Industrial Air Conditioning Investment, by P. J. Marshall (*Heating, Piping and Air Conditioning*, February 1952, p. 71).
- ³²How to Design Exhaust Hoods for Quartz-Fusing Operations, by E. C. Riley et al (*Heating and Ventilating*, April 1940, p. 23).
- ³³A Study of Quartz-Fusing Operations with Reference to Measurement and Control of Silica Fumes, by E. C. Riley and J. M. DallaValle (*U. S. Public Health Reports*, Vol. 54, 1939, p. 532).
- ³⁴Ventilation of Open Tanks, by A. C. Stern (*American Industrial Hygiene Association, Industrial Hygiene Quarterly*, Sept. 1950).
- ³⁵American Standards for Safety in Electric and Gas Welding and Cutting Operations (*American Standards Association*, Z 49.1).
- ³⁶Rules Relating to the Removal of Dust, Gases, and Fumes (*New York State Department of Labor, Industrial Code Rule No. 12*, Jan. 1931).
- ³⁷Energy Losses at Suction Hoods, by A. D. Brandt and R. J. Steffy (*A.S.H.V.E. Transactions*, Vol. 52, 1946, p. 205).
- ³⁸Resistance Test on Pipe, by A. Nutting (*Mechanical Engineering*, May 1938).
- ³⁹Design of Injector for Low Pressure Air Flow, by G. E. McElroy (*U. S. Bureau of Mines, Technical paper 678*).
- ⁴⁰American Standard Safety Code for Ventilation and Operation of Open Surface Tanks (*American Standards Association*, Z 9.1-1951).