PLANT: 1400 HENRY CHEM PLT 309-364-2311 DEPARTMENT: 5537 PVC DISPERSION
EMPLOYEE: YEAR: 1989

JOB CODE / EXPOSURE CDE	JOB NAME / NAME	EXP LVL	RANGE	AVG	STD DEV	UNITS	SAMPLES	DATE	SHIFT	LENGTH	TWA	VALID PROTECTION
1400JT3604	JOB AS TASK OF PVC PROD.OPER.- DRYER OPERATOR											
B0001	NOISE, 80/90-5											
89	AVG EXPOSURE:		033-123	73.96	45.6	PCNT	3					
00064	POLYVINYL CHLORIDE DUST		TOTAL									
89	AVG EXPOSURE:		000-000	0.79	0.0	MG/M3	2					
00148	VINYL CHLORIDE 1910.1017											
89	AVG EXPOSURE:		000-003	0.49	0.5	PPM	37					
	INDIVIDUAL MONITORING:					PPM		03/02/89	A	600	0.29	0 NONE WORN
	INDIVIDUAL MONITORING:					PPM		07/31/89	A	600	0.43	0 NONE WORN
1400553701	PVC PRODUCTION OPERATOR											
B0001	NOISE, 80/90-5											
89	AVG EXPOSURE:		016-152	63.77	41.5	PCNT	8					
00064	POLYVINYL CHLORIDE DUST		TOTAL									
89	AVG EXPOSURE:		000-000	0.48	0.3	MG/M3	3					
00148	VINYL CHLORIDE 1910.1017											
89	AVG EXPOSURE:		000-010	1.30	1.5	PPM	135					
99917	TRAINING - OSHA HAZARD COMMUNICATION											
	INDIVIDUAL MONITORING:							09/21/89	A	60	0.00	0 NONE WORN
99919	TRAINING - HEARING CONSERVATION											
	INDIVIDUAL MONITORING:							11/16/89	A	35	0.00	0 NONE WORN
99931	RESPIRATOR FIT TESTING - QUALITATIVE											
	INDIVIDUAL MONITORING:							05/11/89		15	0.00	0 1/2 MASK - AIR PURIFYING

NGC 09696

PLANT: I400 HENRY CHEM PLT 309-364-2311 DEPARTMENT: 5537 PVC DISPERSION
EMPLOYEE: YEAR: 1988

JOB CODE / EXPOSURE CDE	JOB NAME EXP / NAME	LVL	RANGE	AVG	STD DEV	UNITS	SAMPLES	DATE	SHIFT	LENGTH	TWA	VALID	PROTECTION
1400JT3604	JOB AS TASK OF PVC PROD.OPER.- DRYER OPERATOR												
B0001	NOISE, 80/90-5												
88	AVG EXPOSURE:		013-289	114.58	74.2	PCNT	10						
	INDIVIDUAL MONITORING:					PCNT		06/06/88	A	600	289.20	0	HEARING MUFFS
00064	POLYVINYL CHLORIDE DUST				TOTAL								
88	AVG EXPOSURE:		000-001	1.31	0.8	MG/M3	3						
00148	VINYL CHLORIDE 1910.1017												
88	AVG EXPOSURE:		000-003	0.74	0.8	PPM	48						
	INDIVIDUAL MONITORING:					PPM		02/16/88	A	600	0.59	0	NONE WORN
	INDIVIDUAL MONITORING:					PPM		04/29/88	A	600	0.25	4	NONE WORN
	INDIVIDUAL MONITORING:					PPM		08/19/88	A	600	1.30	0	NONE WORN
	INDIVIDUAL MONITORING:					PPM		09/16/88	A	600	0.34	0	NONE WORN
	INDIVIDUAL MONITORING:					PPM		09/26/88	A	600	0.46	0	NONE WORN
	INDIVIDUAL MONITORING:					PPM		12/09/88	A	600	0.25	4	NONE WORN
1400553701	PVC PRODUCTION OPERATOR												
B0001	NOISE, 80/90-5												
88	AVG EXPOSURE:		006-289	82.02	60.6	PCNT	23						
00064	POLYVINYL CHLORIDE DUST				TOTAL								
88	AVG EXPOSURE:		001-001	1.08	0.0	MG/M3	1						
00148	VINYL CHLORIDE 1910.1017												
88	AVG EXPOSURE:		000-007	0.88	1.2	PPM	131						

NGC 08967

R96846D - S.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/87 TO 12/31/87 DATE 02/25/88 TIME 083727 PAGE 1

CHEMICAL M1 MALE

PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH	RESP HEAR
HENRY	732	000	012	A	031787	600	.33		NO	0
HENRY	732	000	012	A	070987	532	.80		NO	0
HENRY	732	000	012	A	083187	360	.95			0
HENRY	732	000	012	A	090187	360	.29			0
HENRY	732	000	012	A	090387	360	.71			0

R968460 - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/86 TO 12/31/86 DATE 05/09/87 TIME 093257 PAGE 1

CHEMICAL M1 MALE

PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH	RESP	YEAR
HENRY	732	CCC	C12	C	060486	360	1.34			0	
HENRY	732	CCC	C12	D	071186	360	.25	< D LIMT	2	C	
HENRY	732	CCC	C12	A	090486	360	.39		NE	1	

SOUND N80 MALE

PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	VALUE	> 115DB	YEAR
HENRY	731	CCC	C19	B	061986	360	36.80		2

NGC 08969

R96846D - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/85 TO 12/31/85 DATE 05/01/86 TIME 092054 PAGE 1

CHEMICAL M1 MALE

PLANT	NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH	RESP HEAR
HENRY		732	000	012	D	020585	360	.30		NO	0
HENRY		732	000	012	A	050385	360	.40			2

NGC 08970

96846D - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/84 TO 12/31/84 DATE 02/01/85 TIME 152103 PAGE 1

CHEMICAL M1 MALE

PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH	RESP	HEAR
HENRY	732	000	012	D	020384	360	1.95	OUT MASK	NO	0	
HENRY	732	000	012	D	020964	240	.43	OUT MASK	NO	0	
HENRY	732	000	012	A	021084	360	.21	< D LIMT	NO	0	
HENRY	732	000	012	A	022284	360	.62	OUT MASK	NO	0	
HENRY	732	000	012	D	022484	360	1.21	OUT MASK	NO	0	
HENRY	732	000	012	A	032284	360	.00	< D LIMT	NO	0	
HENRY	732	000	012	D	032284	360	.00	< D LIMT	NO	0	
HENRY	732	000	012	D	040384	360	.20	< D LIMT	NO	0	

SOUND N80 MALE

PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	VALUE	> 115DB	HEAR
HENRY	732	000	012	A	022184	360	10.00	YES	2

NGC 08971

R966469 - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/83 TO 12/31/83 DATE 02/17/84 TIME 102643 PAGE 1

CHEMICAL M1 MALE

PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK	TH RESP	HEAR
HENRY	732	000	C12	D	111783	360	.76	OUT MASK	NO	0	
HENRY	732	000	C12	D	121283	195	4.16	OUT MASK	NO	0	

NGC 08972

CHEMICAL M1 MALE

NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH	RESP
	732	000	012	C	011282	360	.00	OUT MASK	NO	0
	732	000	012	C	021182	360	.03	OUT MASK	NO	0
	732	000	012	C	030982	360	.22	OUT MASK	NO	0
	732	000	012	C	040882	360	.07	OUT MASK	NO	0
	732	000	012	C	050582	360	.02	OUT MASK	NO	0

SOUND NBO MALE

NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	VALUE	> 115DB
	732	000	012	C	010682	360	59.00	

R968460 - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/81 TO 12/31/81 DATE 01/10/86 TIME 105352 PAGE 1

CHEMICAL M1 MALE

PLANT	NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH	RESP HEA
HENRY		732	000	012	C	011481	360	.27	OUT MASK	NO	0
HENRY		732	000	012	C	021281	360	2.79	OUT MASK	NO	0
HENRY		732	000	012	C	031081	360	.08	OUT MASK	NO	0
HENRY		732	000	012	C	040781	360	.05	OUT MASK	NO	0
HENRY		732	000	012	C	050581	360	.74	OUT MASK	NO	0
HENRY		732	000	012	C	062281	600	.08	OUT MASK	NO	0
HENRY		732	000	012	C	071881	600	.22	OUT MASK	NO	0
HENRY		732	000	012	C	081481	600	.06	OUT MASK	NO	0
HENRY		732	000	012	C	091481	600	.04	OUT MASK	NO	0
HENRY		732	000	012	C	101181	600	.00	OUT MASK	NO	0
HENRY		732	000	012	C	110781	360	.00	OUT MASK	NO	0
HENRY		732	000	012	C	120581	360	.86	OUT MASK	NO	0

2966460 - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/80 TO 12/31/80 DATE 02/17/81 TIME 141721 PAGE 1

CHEMICAL M1 MALE

PLANT	NAME----	AREA	TASK	JOB	SHIFT	DATE..	E/T	---PPM	PUMP POS	BRK TH	RESP
HENRY		732	000	012	C	011280	360	.01	OUT MASK	NO	0
HENRY		732	000	012	C	021280	360	3.03	OUT MASK	NO	0
HENRY		732	000	012	C	030280	360	.06	OUT MASK	NO	0
HENRY		732	000	020	A	041680	360	.22	OUT MASK	NO	0
HENRY		732	000	021	B	051580	360	.07	OUT MASK	NO	0
HENRY		732	000	021	D	060480	360	.07	OUT MASK	>20%	0
HENRY		732	000	020	C	082080	360	.00	OUT MASK	NO	0
HENRY		732	000	012	C	082880	360	.01	OUT MASK	NO	0
HENRY		732	000	012	C	091380	360	.04	OUT MASK	NO	0
HENRY		732	000	012	C	100480	360	.10	OUT MASK	NO	0
HENRY		732	000	012	C	111280	360	1.01	OUT MASK	>20%	0

CHEMICAL 0065 MALE

PLANT	NAME----	AREA	TASK	JOB	SHIFT	DATE..	E/T	VALUE	PUMP POS	BRK TH	RESP
HENRY		732	000	020	B	051580	360	1.26			0
HENRY		732	000	020	B	061280	360	.12			0
HENRY		732	000	020	D	063080	360	.00			0
HENRY		732	000	020	D	070280	360	.00			0
HENRY		732	000	012	C	090890	780	3.88			0

NGC 08975

R96846D - R.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/79 TO 12/31/79 DATE 03/27/80 TIME 115946 PAGE 1

CHEMICAL M1 MALE

PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH	RE
HENRY	732	C00	012	C	011379	360	.74	OUT MASK	NO	
HENRY	732	C00	C12	C	022779	360	.03	OUT MASK	NO	
HENRY	732	C00	012	C	031579	360	.01	OUT MASK	NO	
HENRY	732	C00	012	C	041879	360	.29	OUT MASK	NO	
HENRY	732	C00	C12	C	052279	360	.49	OUT MASK	NO	
HENRY	732	000	012	C	061479	360	1.71	OUT MASK	NO	
HENRY	732	C00	012	C	081879	360	.00	OUT MASK	NO	
HENRY	732	C00	012	C	090779	360	.08	OUT MASK	NO	
HENRY	732	000	012	C	100579	360	.16	OUT MASK	NO	
HENRY	732	C00	012	C	110579	360	.50	OUT MASK	>20%	
HENRY	732	C00	012	C	120879	360	.14	OUT MASK	NO	

NGC 08976

R96846D - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/78 TO 12/31/78 DATE 01/19/79 TIME 080117 PAGE 1

CHEMICAL M1 MALE

PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH
HENRY	732	000	012	C	081278	360	.51	OUT MASK	NO
HENRY	732	000	012	C	010778	360	1.12	OUT MASK	NO
HENRY	732	000	012	C	021278	360	2.03	OUT MASK	NO
HENRY	732	000	012	C	022878	360	.01	OUT MASK	>20%
HENRY	732	000	012	C	030778	360	.98	OUT MASK	NO
HENRY	732	000	012	C	031778	360	.48	OUT MASK	NO
HENRY	732	000	012	C	033178	360	1.50	OUT MASK	NO
HENRY	732	000	012	C	040678	360	.37	OUT MASK	NO
HENRY	732	000	012	C	041378	360	.09	OUT MASK	NO
HENRY	732	000	012	C	042878	360	.16	OUT MASK	NO
HENRY	732	000	012	C	050678	360	.01	OUT MASK	NO
HENRY	732	000	012	C	051278	360	.02	OUT MASK	NO
HENRY	732	000	012	C	051978	360	.09	OUT MASK	NO
HENRY	732	000	012	C	060778	360	.12	OUT MASK	NO
HENRY	732	000	012	C	090778	360	.01	OUT MASK	NO
HENRY	732	000	012	C	100978	360	.55	OUT MASK	NO
HENRY	732	000	012	C	110678	360	.25	OUT MASK	NO

68460 - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/77 TO 12/31/77 DATE 01/04/78 TIME 131644 PAGE 1

CHEMICAL M1 MALE

ANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK TH	RESP
NRY	732	000	012	C	010377	360	.48	OUT MASK	>20%	0
NRY	732	000	012	C	021277	360	.94	OUT MASK	NO	0
NRY	732	000	012	C	031577	360	1.89	OUT MASK	>20%	2
NRY	732	000	012	C	032877	360	.19	OUT MASK	NO	0
NRY	732	000	012	C	050777	360	.12	OUT MASK	NO	0
NRY	732	000	012	C	081077	360	.08	OUT MASK	>20%	0
NRY	732	000	012	C	092577	360	3.59	OUT MASK	NO	0
NRY	732	000	012	C	101177	360	.72	OUT MASK	NO	0
NRY	732	000	012	C	110477	360	.00	OUT MASK	>20%	0

NQC 08978

R96846D - B.F.G. PERSONNEL MONITOR - PERSONAL DATA
01/01/76 TO 12/31/76 DATE 03/10/77 TIME 120230 PAGE 1

CHEMICAL M1

PLANT NAME....	AREA	TASK	JOB	SHIFT	DATE..	E/T	...PPM	PUMP POS	BRK
HENRY	732	000	012	C	012276	360	.25		
HENRY	732	000	012	C	022676	360	.15		
HENRY	732	000	012	C	032476	360	.31	OUT MASK	NO
HENRY	732	000	012	C	042376	360	.89		
HENRY	732	000	012	C	052376	360	.34		
HENRY	732	000	012	C	062276	360	.14	OUT MASK	NO
HENRY	732	000	012	C	072476	360	.00		
HENRY	732	000	012	C	083176	360	.00		
HENRY	732	000	012	C	091476	360	.25		
HENRY	732	000	012	C	102476	360	.43	OUT MASK	>20%
HENRY	732	000	012	C	112276	360	.42	OUT MASK	>20%
HENRY	732	000	012	C	120776	360	.03	OUT MASK	NO

NGC 08979

STRIBUTION ATTENTION M.I.S. DEPARTMENT

****
* B F G R E S
****

R96846 VCM MONITORING - PERSONAL RECORD DATE 01/15/76

FROM 01/01/75 TO 12/31/75

PLANT NAME	SPL.PERIOD	AREA	TASK	JOB	SHIFT	DATE	EXPO.TIME	PM-VCM	R
HENRY	LONG	732	000	012	C	020275	240	0.08	1
HENRY	LONG	732	000	012	C	030275	240	0.08	0
HENRY	LONG	732	000	012	C	033175	240	0.00	1
HENRY	LONG	732	000	012	C	041275	240	0.07	1
HENRY	LONG	731	000	012	C	052175	360	0.01	2
HENRY	LONG	732	000	012	C	062275	360	0.02	2
HENRY	LONG	731	000	012	C	070775	360	0.02	2
HENRY	LONG	732	000	012	C	092075	360	0.15	0
HENRY	LONG	732	000	012	C	102575	360	0.22	0
HENRY	LONG	732	000	012	C	112475	360	0.22	0
HENRY	LONG	732	000	012	C	122475	360	0.34	0

NGC 08980