

VCM Tankfarm HAZOP		# 94012
Critical Rank:	4,	Marginal Risk
	III =	Medium Consequence
	B =	Probable Occurrence
Deviation: High temperature.		
Equipment Number: PP-270 & PP-219.		
Equipment Description: Node #6 ; P&ID # VS-090105-PID-D. Transfer pump glycol pot and recovery line.		
Cause: 1. Blocked flow. 2. External heat.		
Consequence: 1. Damage piping. 2. Inadequate cooling. 3. Seal failure. 4. Can't recover pumps. 5. Possible VCM release.		
Suggested Mitigation: The team has no suggestions.		
Resolution:		
Comments:		