

WARNING

INHALATION OF AIR-BORN ASBESTOS FIBERS MAY CAUSE ASBESTOSIS OR OTHER SERIOUS BODILY HARM.

SOME GASKETS CONTAIN ASBESTOS; THUS, CARE SHOULD BE TAKEN TO AVOID CREATING AIR-BORN FIBERS OR DUST WHEN REMOVING OLD GASKET MATERIAL FROM AN ENGINE. IF ASBESTOS FIBERS OR DUST BECOME AIR-BORN, FOLLOW OSHA SAFETY PRACTICES, INCLUDING THE USE OF PROPER DUST CONTROL EQUIPMENT.

THE ASBESTOS, AS USED IN GASKETS, IS USUALLY ENCAPSULATED IN A RUBBER COMPOUND AND PRESENTS A POTENTIAL DANGER WHEN AND IF THE GASKET IS DESTROYED DURING INSTALLATION OR REMOVAL.

DANA-027

PRIV 04341