

**UNION
CARBIDE**

WV-0191 # 145

UNION CARBIDE CORPORATION

P. O. BOX 8004, SOUTH CHARLESTON, W. VA. 25303

Silicones and Urethane Intermediates

South Charleston Plant

PLAINTIFF'S EXHIBIT

UC-2290

ASBESTOS ESTIMATE

DEPARTMENT: *The Fire Tower South Side Of Upperbridge*

INSULATOR MAN-HOURS ESTIMATE:

ACTUAL MAN-HOURS: *388*

ESTIMATED COST:

The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.

With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.

Priority 1 is insulation in very bad condition with a high degree of exposure.

Priority 2 is insulation needing attention but with less immediate risk of exposure.

COLOR CODE - This signifies the work necessary.

Blue - Cover and/or patch existing insulation.

Green - Strip and reinsulate.

Red - Strip only.

All of the insulation pictured has been spray painted with the appropriate color.



UNION CARBIDE CORPORATION

P. O. BOX 8004, SOUTH CHARLESTON, W. VA. 25303

Silicones and Urethane Intermediates
South Charleston Plant

ASBESTOS ESTIMATE

DEPARTMENT: *Loading Rack North Of 209 Shed*

INSULATOR MAN-HOURS ESTIMATE:

ACTUAL MAN-HOURS:

ESTIMATED COST:

The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.

With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.

Priority 1 is insulation in very bad condition with a high degree of exposure.

Priority 2 is insulation needing attention but with less immediate risk of exposure.

COLOR CODE - This signifies the work necessary.

Blue - Cover and/or patch existing insulation.

Green - Strip and reinsulate.

Red - Strip only.

All of the insulation pictured has been spray painted with the appropriate color.



UNION CARBIDE CORPORATION

P. O. BOX 8004, SOUTH CHARLESTON, W. VA. 25303
Silicones and Urethane Intermediates
South Charleston Plant

ASBESTOS ESTIMATE

DEPARTMENT: *Bldgs. 4-2*

INSULATOR MANHOURS ESTIMATE:

ACTUAL MANHOURS: *7116*

ESTIMATED COST:

The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.

With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.

Priority 1 is insulation in very bad condition with a high degree of exposure.

Priority 2 is insulation needing attention but with less immediate risk of exposure.

COLOR CODE - This signifies the work necessary.

Blue - Cover and/or patch existing insulation.

Green - Strip and reinsulate.

Red - Strip only.

All of the insulation pictured has been spray painted with the appropriate color.

UNION CARBIDE CORPORATION

P. O. BOX 8004, SOUTH CHARLESTON, W. VA. 25303

Silicones and Urethane Intermediates

South Charleston Plant

ASBESTOS ESTIMATE

DEPARTMENT: *Blug. #75*

INSULATOR MANHOURS ESTIMATE:

ACTUAL MANHOURS: 200

ESTIMATED COST:

The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.

With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.

Priority 1 is insulation in very bad condition with a high degree of exposure.

Priority 2 is insulation needing attention but with less immediate risk of exposure.

COLOR CODE - This signifies the work necessary.

Blue - Cover and/or patch existing insulation.

Green - Strip and reinsulate.

Red - Strip only.

All of the insulation pictured has been spray painted with the appropriate color.

**UNION
CARBIDE**

UNION CARBIDE CORPORATION

P. O. BOX 8004, SOUTH CHARLESTON, W. VA. 25303

Silicones and Urethane Intermediates

South Charleston Plant

ASBESTOS ESTIMATE

DEPARTMENT: *Cafeteria, Bldg. #314 - Garage, Bldg. #428*

INSULATOR MANHOURS ESTIMATE:

ACTUAL MANHOURS:

ESTIMATED COST:

The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.

With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.

Priority 1 is insulation in very bad condition with a high degree of exposure.

Priority 2 is insulation needing attention but with less immediate risk of exposure.

COLOR CODE - This signifies the work necessary.

Blue - Cover and/or patch existing insulation.

Green - Strip and reinsulate.

Red - Strip only.

All of the insulation pictured has been spray painted with the appropriate color.



UNION CARBIDE CORPORATION

P. O. BOX 8004, SOUTH CHARLESTON, W. VA. 25303

Silicones and Urethane Intermediates
South Charleston Plant

ASBESTOS ESTIMATE

DEPARTMENT: *Paint Shop*

INSULATOR MANHOURS ESTIMATE:

ACTUAL MANHOURS: *80 M.H.*

ESTIMATED COST:

The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.

With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.

Priority 1 is insulation in very bad condition with a high degree of exposure.

Priority 2 is insulation needing attention but with less immediate risk of exposure.

COLOR CODE - This signifies the work necessary.

Blue - Cover and/or patch existing insulation.

Green - Strip and reinsulate.

Red - Strip only.

All of the insulation pictured has been spray painted with the appropriate color.



UNION CARBIDE CORPORATION

P. O. BOX 8004, SOUTH CHARLESTON, W. VA. 25303

Silicones and Urethane Intermediates

South Charleston Plant

ASBESTOS ESTIMATE

DEPARTMENT: 426

INSULATOR MANHOURS ESTIMATE: 280

ACTUAL MANHOURS:

ESTIMATED COST:

The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.

With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.

Priority 1 is insulation in very bad condition with a high degree of exposure.

Priority 2 is insulation needing attention but with less immediate risk of exposure.

COLOR CODE - This signifies the work necessary.

Blue - Cover and/or patch existing insulation.

Green - Strip and reinsulate.



Red - Strip only.

All of the insulation pictured has been spray painted with the appropriate color.

WV-0191 #146

BLOG-S

103-216



UCC 002254



UNION CARBIDE CORPORATION
P. O. BOX 8004, SOUTH CHARLESTON, W. VA. 25303
Silicones and Urethane Intermediates
South Charleston Plant

ASBESTOS ESTIMATE

DEPARTMENT:

INSULATOR MANHOURS ESTIMATE:

ACTUAL MANHOURS:

ESTIMATED COST:

The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.

With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.

Priority 1 is insulation in very bad condition with a high degree of exposure.

Priority 2 is insulation needing attention but with less immediate risk of exposure.

COLOR CODE - This signifies the work necessary.

Blue - Cover and/or patch existing insulation.

Green - Strip and reinsulate.

Red - Strip only.

All of the insulation pictured has been spray painted with the appropriate color.



PICTURE: Left

DISCRIPTION: Unused line at stairway
on the N/W corner of bldg. 195.


COLOR CODED: Red
MANHOURS REQUIRED: 24
PRIORITY: 1

PICTURE: Below


DISCRIPTION: Two lines at stairway on
the N/W corner of bldg. 195.

PRIORITY: 1
COLOR CODED: Red
MANHOURS REQUIRED: 32



195



BIDG
152,



UCC 002257



UCC 002258

BLDG.
152