

NEW JERSEY MANUFACTURING
INSURANCE COMPANY
TRENTON, NEW JERSEY 08607

PLAINTIFF'S EXHIBIT

Q-946

Joe:
Take care of
and then let me
know.

September 23, 1969

AREA CODE 609
883-1300

Major 9/29/69
Quigley Company Inc
Bordentown Avenue
Old Bridge, N J 08857

Att: Mr Jack Major

Dear Mr Major:

On 9/19/69 Mr John Bratt of our Engineering Department made a routine safety inspection of your plant, and was shown thru by your Mr Joe Kloc. The following recommendations are offered:

(1) Correct reversed polarities noted at the following locations:

South Wall, experimental kiln building
Mud Mill
Electrical Shop

(2) Provide 3-prong plugs for drill and grinder in gun department. If it is necessary for employees to use these tools at field locations where a matching outlet is not available, an adapter should be used and the "pigtail" of the adapter fastened to the screw of the outlet cover plate.

(3) Secure gate at extruder drive.

(4) You should guard inlet and outlet of cool air blower at kiln.

(5) Scrap defective ladder.

We are greatly concerned at the manner that your lift trucks are operated. There are many signs of damage to structures which indicate speed and carelessness. We urge that you take whatever steps are necessary to ensure safe operation of these vehicles before a serious accident occurs.

Continuation Sheet

New Jersey Manufacturers
Insurance Company

Quigley Company Inc.
#2

If we can be of any further service, please
do not hesitate to call upon us.

Very truly yours,

NEW JERSEY MANUFACTURERS INSURANCE COMPANY

AOP/sms

A. O. Persson
A O Persson
Chief Engineer