



Inter Office Communication

Automotive Assembly Division
Metuchen Assembly Plant

October 24, 1972

TO: Mr. R. H. Yapp
Safety & Security Coordinator
Personnel Services Department

SUBJECT: 6599.59 - Exposure to Asbestos Dust.

In reply to your letter, October 4, 1972, the following survey was conducted at the Metuchen Assembly Plant.

A. Cutting and drilling of asbestos cement sheets and pipe.

None

B. Handling or reworking of asbestos-containing production parts.

None

C. Workers exposed to high temperature pipe insulation containing asbestos.

Power House Employes

1. N. J. State Boiler Inspection (3 boilers)
2. 2 Days (8 hours) per boiler - 2 men
3. 6 Days per year

D. Asbestos powder or impregnated heat shields used in final paint repair.

None

E. Sprayed on asbestos building insulation.

None

8005 0261

177

PRODUCED BY FORD

Inter Office Communication

Automotive Assembly Division
Metuchen Assembly Plant

October 24, 1972

SUBJECT: 6599.59 - Exposure to Asbestos Dust. - continued.

F. Other sources not enumerated including exposure from contractor's work.

Power House (Contractors)

1. Inducer fan insulation for boiler
   Once each year
   5 Days - 2 Men - 8 Hours

2. Hot water heater
   Once each year
   5 Days - 2 Men - 8 Hours

E. A. Maypother
Safety Engineer
Metuchen Assembly Plant

8005 0262

177

PRODUCED BY FORD