

SERVICE BULLETIN

DECEMBER 2, 1977

T

No. Q92

under

BRAKES

FOR BRANCHES, DISTRIBUTORS AND CUSTOMERS.

CHASSIS AFFECTED ALLENTOWN ☒ HAYWARD ☒ OAKVILLE ☒

BRAKE SHOE RETURN SPRING

(RAS512C, RAD529C, RAD530C, R170C, L155C Rear Axles and
SW56C, SW57C, SW571C, SW573C, SW76C Bogies with
Rockwell International 16 1/2 x 7 Cam Brakes)

PURPOSE To inform the field of an improved spring.

RECOMMENDATION Install the new spring when replacement is required.

INFORMATION The improved brake shoe return spring is made of high tensile steel for increased service life. Part number is 8235-2258-U-619 and it replaces spring 364SM27. The new spring is painted blue for identification.

CIRCULATION

Service Manager	
Shop Foreman	
Night Foreman	
Night Foreman	
Inspector Leadman	
Inspector Leadman	
Inspector Leadman	
Unit Overhaul Room	
Shop Office	