Monsanto

Monsanto Company
800 N. Lindbergh Boulevard
St. Louis, Missouri 63166
Phone: (314) 694-1000

May, 1970

Direct Customer

Dear Customer:

You have received our letter mailed February 27, 1970 notifying you of the allegations that certain polychlorinated biphenyls (PCBs) had been found in the environment and were contaminants. Since that time, other reports concerning PCBs have been published. An examination of the PCB matter has indicated that their use in synthetic resin compositions may be a source of the alleged environmental contamination.

Monsanto has sold PCB-containing materials under the trade name of Aroclor®. These Aroclors® included:

Aroclor® 1232
Aroclor® 1242
Aroclor® 1248
Aroclor® 1254
Aroclor® 1260
Aroclor® 1262
Aroclor® 1268
Aroclor® 4465
Aroclor® 1100 Series
Montar® 1

Toluene or xylene blends of the above products also contained PCB.

In review of the allegations which have been made concerning PCBs, and being a concerned and responsible member of the world community, we have come to a decision to discontinue the sale of PCB-containing products for modifier and plasticizer applications effective August 30, 1970.

Recognizing that this action will result in research effort on your part to find adequate replacements, we have prepared a series of data sheets outlining suggested alternatives for most applications. Copies of the report for your application may be obtained by calling the regional office closest to you as shown on the attached sheet.

We urge that you consider initiating now any necessary work on your part to effect the change to a new material. We stand ready to assist you in any way possible.

Very truly yours,

W. E. Schalk
Director of Sales
Plasticizers

/dbw

Attachment

MONSANTO COMPANY
REGIONAL SALES OFFICES

Akron Marketing & Research Center
260 Springside Drive
P. O. Box 5444
Akron, Ohio 44313
(216) 666-4111

Chicago Sales Office
3158 Des Plaines Avenue
Des Plaines, Illinois 60018
(132) 296-6688

Boston Sales Office
Everett Station
Boston, Massachusetts 02149
(617) 387-5010

New York Sales Office
277 Park Avenue
New York, New York 10017
(212) 922-4111

St. Louis Sales Office
800 North Lindbergh
St. Louis, Missouri 63166
(314) 694-1000

Wilmington Sales Office
2005 Concord Pike
Wilmington, Delaware 19803
(302) 658-6531

REPLACEMENT SUGGESTIONS FOR MONSANTO AROCLORS

sin	Application	Product Presently Used							Suggested Replacements
		1232	1242	1248	1254	1260	1262	1268	
olysulfide	Automotive - Thermoset Acrylics			X	X				Santicizer 679, Santicizer 213, Aroclor 5442 or Aroclor 5460 with Santicizer 261 in this order. Bentonite may have to be used with Santicizer 679 and Santicizer 213 as a thickener.
	Light Construction			X	X	X	X		Replace Aroclor 1248 ar Aroclor 1254 with Santi cizer 261. Or use Aroc 5442/5460 blends with Santicizer 160/261 to replace Aroclors 1248, 1254, 1260, 1262.
Chlorinated Rubber	Coatings			X	X	X			Where resistance to concentrated H_2SO_4 is required, use 2/1 ble of Aroclor 5460/5442. In other applications use 2/1 blends of Arc 5460 and Santicizer Santicizer 261, Sant cizer 711.
	Adhesives				X	X			Blends of Aroclor 54 Santicizer 160 or Sa cizer 261.

MONS 089280

REPLACEMENT SUGGESTIONS FOR MONSANTO AROCLORS

Resin	Application	Product Presently Used							Suggested Replacements
		1232	1242	1248	1254	1260	1262	1268	
Styrene Butadiene Rubber	Coatings				X				See chlorinated rubber, coatings for suggested starting points.
	Adhesives	X	X	X	X				DBP, Santicizer 160, Aroclor 1221
Polyvinyl Acetate	Emulsion Adhesives	X	X	X	X				Santicizer 218-A/885, Santicizer 160, Aroclor 1221, Santicizer 148
	Hot Melt Adhesives			X	X				Santicizer 160
								X	This is a flame retard filler with good heat tortion characteristic Possible replacements Aroclor 1268 might be Aroclor 5460, TPP, Phogard C-22-R, 2XC-20 (Development product)
Other	Miscellaneous	X	X	X	X	X	X		A 62% Aroclor 5460/38% Aroclor 1221 blend giv viscosity equal to Arc 1254. Maximum Aroclor 5460 concentration possible is 70%. High concentrations do not allow solution of Aroc 5460 in Aroclor 1221.

MONS 089290