AFR -0-81-D-1037

TST. WGT. 3371 LBS.

OK / AP

(E) 10-10-8	DWG 11-18-7
TYPED BY	
JLC 11-24-76	

MAKING NOTES

REMARKS

AME: MOLYBDATE ORANGE NON-BLEEDING

-PRESSING-

INSTRUCTIONS					
AT			241		
ATE			4-13-81		
IME			6:45 PM		
ELEASED BY					
RESS	2	91	92	93	
O. OF CAKES	32	42	32	32	

RESS with AGITATION

ASH TO 2000 OHMS with 35-75°F water

EST AFTER 2 HOURS

OAD on 4 cars

AMPLES

ELIVER TO

BLL

RECORD					
PRESSLOAD	1ST	2ND	3RD	4TH	5TH
STARTED	8 PM				
CAKES USED	32				
WATER ON	1AM				
HRS. WASHED	3				
OHMS	2500				
HRS. WASHED					
OHMS					
HRS. WASHED					
OHMS					
CAKE CONDITION					
NO. CARS LOADED	4				

EXPLAIN LOSSES

SAMPLED BY RELEASED BY

-DRYING-

XTRUDED) DRY 12 HOURS AT 240°F

OT EXTRUDED) DRY 14 HOURS AT 240°F

AMPLES

LIVER TO

LUMP: - OK - WET - SALTS - CONTAMINATE

ADDITIONAL DRYING HOURS REQUIRED

No Drums 11

NO. CARS PULLED LUMP WGT. 3413

SAMPLED BY RELEASED BY

-GRINDING-

ILL Mikroatomize SCREEN RPM

AX. TEMP. °F

SET ROOF BLAST GATE AT "9" FOR HIGH AIR FLOW

AMPLE A... / WITHOUT MIXING

AMPLES 1 Env

LIVER TO C T L

SCREEN RPM

MAX. TEMP. °F

EXPLAIN LOSSES

DATE MIXED

SAMPLED BY RELEASED BY

1037
41
17

0.00 *

3.19 +
0.12 -
3.45 +
0.12 -
3.26 +
0.12 -
3.40 +
0.12 -
3.16 +
0.12 -
3.31 +
0.12 -
3.28 +
0.12 -
3.32 +
0.12 -
3.47 +
0.12 -
3.18 +
0.12 -
2.43 +
0.12 -
34.13 *

DUP050096069