

1 Q Picking up on what we discussed previously
2 about service manuals, you mentioned to your knowledge
3 a service manual only contained an asbestos warning in
4 1973 and no warnings were contained in service manuals
5 thereafter, correct?

6 A Yes.

7 Q I would like you to look at the second
8 page of the document marked P-2 and ask you to read
9 paragraph 2 and see if that refreshes your recollection
10 that maybe some manuals after 1973 did contain
11 warnings.

12 A "Service manuals, according to our service
13 publications department, for 1984 domestic passenger
14 car and truck models, contain asbestos warnings in the
15 brake and clutch section, asbestos warnings in the
16 import service manuals are on the agenda for discussion
17 with Mitsubishi Motors during November 1983 by Chrysler
18 to Japan, copies of the warnings and the domestic
19 service manuals are attached."

20 Q. Does that refresh your recollection there
21 was a warning in the 1984 service manual?

22 A It doesn't refresh my recollection because I
23 don't have any recollection. I've not seen an '84 or
24 subsequent manual.

25 Q When you reviewed the service manuals, you