

GRACE Policy and Organization Guide

09.05

Subject Asbestos-Containing Materials in Grace Premises	Policy no. 422	Page 5 of 6
	Date approved July 14, 1988	Approved by <i>[Signature]</i>

WRG 002159

Asbestos Action Notification Information

RECEIVED
DEC 08 1989
R. C. FINKE

1. Date of notification 12/11/89
2. Group
3. Division GSC
4. Facility involved
 - a. name Washington Research Center
 - b. street address 7329 Rt 32
 - c. city Columbia
 - d. country Howard
 - e. state Maryland
 - f. country
 - g. postal code 21044
5. Facility Manager
 - a. name William J. Kodd
 - b. business phone number (301) 531-4647
6. Primary Contact
 - a. name Abone
 - b. business phone number
 - c. facsimile phone number (301) 531-4141
7. Type of material—check all applicable:
 - a. Fireproofing
 - b. Boiler insulation
 - c. Pipe insulation
 - d. Corrugated siding
 - e. Roofing shingles
 - f. Ceiling plaster ☒ USG product
 - g. Ceiling tiles
 - h. Floor tiles
 - i. Wallboard
 - j. Other
8. Location within facility Bld 1A - LIBRARY - Rm 176
9. Approximate date of installation (if known) 1968



8 pages

TO: MR RICHARD FINKE, ESQ.

FROM: MR WILLIAM KODL

Richard:

i know.
i should
not proceed
with Marcor,
~~Marcor~~

job must start
12/26/89.

Thanks
Bill

301-531-
4647

GRACE Policy and Organization Guide

Subject Asbestos-Containing Materials in Grace Premises	Policy no. 422	Page 6 of 6
	Date approved July 14, 1989	Approved by <i>[Signature]</i>

10. Approximate quantity/extent of material **1300 ft²**
11. Present condition; description of inspection/testing to date **FAR**
(Survey recommended abatement ASAP)
12. Action is (check one): not yet commenced in progress, completed, not recommended
13. Description of scope and cost of action taken/planned to be taken **REMOVAL**
(See Below)
14. Date(s) action taken/planned to be taken **12/26-12/30/89** *****
15. Reason(s) for action (check-off with added description):
- a. Product performance failure
 - ☒ b. Quality/appearance deterioration
 - c. Replacement of machinery
 - d. Building demolition
 - e. Renovation (ACM removal mandatory)
 - f. Renovation (ACM removal optional)
 - g. Emergency repair
16. Other evidence attached (e.g. photographs, inspection reports, test results, etc.) *Photos + test results from survey (not attached) recommended abatement due to library usage +*
17. Contractor(s) involved (name, address, phone, function of each) *potential hazards*

MARCOR of Maryland Inc.

P.O. Box 1043

Hunt Valley, Md. 21030-6043

(301) 765-2525

***** Option # 3 is preferred due to low cost, timing, & the fact that encapsulation may not eliminate the potential hazards.
William J. Hall