

FORMULA SUPPLEMENT

T-E-M-P-O-R-A-R-Y

APPROVAL:

Ind. Hyg. H. A. Eschenbach
 Tech. Admin. D. O'Donnell
 Qual. Assur. R. C. Ericson

PRODUCT
CODE NO.

THIS DRAFT CANCELS
PRIOR DRAFT NO. CV-1039 -2

(1) CM (2) dad (2) (4)

PRODUCT Terra-Lite Forestry Mix

PLANT NAME Vancouver

DRAFT NO. CV-1068

DATE July 14, 1981

In case of an accident or any other emergency, call CHEMTREC at 800-424-9300 for instructions on handling hazardous materials. CHEMTREC operates 24 hours per day, 7 days per week.

PACKAGING:

CONTAINER SIZE

CPD SPEC. NO.

APPROX. NET

SHIPPING WT.

LABELLING & STENCILLING REQUIREMENTS

113L

MM20V

12kg.

	SIDE	TOP
Product	☐	☐
Special Warning Label	☐	☐
Keep From Freezing	☐	☐
Stir Well	☐	☐
Address	☐	☐
Other	☐	☐



NOTES, SAFE PRACTICE & STORAGE

Saybolt Visc. _____
 Flash Point _____
 Pensky-Martens C.C. _____
 Tagliabue C.C. _____
 Setflash _____
 Vapor Pressure @ 100°F. _____
 Handling & Storage Requirements _____

BILL OF LADING REQUIREMENTS

D.O.T. Class (1) _____
 D.O.T. Article (2) _____
 Freight Classification _____
 Spec. B/L Marking _____

HAZARDOUS MATERIALS HANDLING INSTRUCTIONS

The following safety equipment is recommended for use where appropriate: respirators meeting MESA/NIOSH 21C requirements for dusts and 23C requirements for vapor, gas, mist, or fumes; chemical goggles with baffles & anti-fog treatment.

HAZARDOUS MATERIALS	SAFETY PRECAUTIONS
Vermiculite	Libby: Avoid breathing dust. TLV: Airborne tremolite asbestos fiber 2f/ml. TWA 15 minute ceiling 10f/ml. Nuisance dust respirable fraction 5 mgm/m ³ . Total dust 15 mgm/m ³
SNAD	Avoid breathing dust; use a respirator. TLV depends upon silica content, but may be as low as 1 mg/m ³
	15193742

- (1) Refer to D.O.T. Section 172.4
 (2) Refer to D.O.T. Section 172.5

TLV=Threshold Limit Value (A concentration, usually airborne, of a substance to which a person may be safely exposed.) It may be expressed as a Time-Weighted-Average (TWA) for an 8-hour day and a 40-hour week, or in some cases as a ceiling limit (C).