
174-STEERING IDLER ARM REPAIR KITS


NYLON BUSHINGS w/Ball Bearings



3-5797
3-5817


Employs longer lasting Nylon Bushings in place of original Rubber Bushings

STEEL SPRING w/Rubber Bushing



3-5809

RUBBER BUSHINGS w/Ball Bearings



3-5810
3-5811
3-5848

Car	Years	Models	Nylon Bushing	Steel Spring	Rubber Bushing
BUICK	57-60	All	------	------	**3-5848**
	54-56	All	------	**3-5809**	**3-5810**
BUICK SPECIAL	61-62	All	------	**3-5809**	**3-5810**
CADILLAC	50-60	All	------	**3-5809**	**3-5810**
	37-49	All	------	**3-5809**	**3-5810**
CHEVROLET	58-60	All	**3-5797**	------	------
	55-57	All	**3-5817**	------	------
CHEVY II	1962	All	------	------	**3-5811**
CHRYSLER	55-56	All	------	**3-5809**	------
DESOTO	55-56	All	------	**3-5809**	------
DODGE	55-56	All (Ex. 6 Cylinder)	------	**3-5809**	**3-5811**
	53-54	All (Ex. 6 Cylinder)	------	**3-5809**	**3-5810**
EDSEL	1958	Ranger, Pacer w/o Power Steering	------	------	**3-5811**
FORD	49-60	All (Ex. Power Steering)	------	**3-5809**	**3-5811**
F-85	61-62	All	------	------	**3-5810**
	1961	All	------	**3-5809**	------
HUDSON	55-57	6 & 8 Cyl. Wasp & Hornet	------	------	**3-5810**
LINCOLN	1955	All	------	------	**3-5811**
	49-54	All	------	**3-5809**	**3-5811**
MERCURY	49-60	All (Ex. Power Steering)	------	**3-5809**	**3-5811**