SECTION 1

PAINTING (Sprinkler Piping)

1. SCOPE

1.1 The work to be performed by the Contractor, under this section of these specifications, is the surface preparation and the application of paint to the surface of all materials except sprinkler heads.

2. SURFACE PREPARATION

2.1 All surfaces to which paint is to be applied shall first be solvent and hand cleaned per SSPC - SP 1-63 and SSPC - SP 2-63.

2.2 Soluble or loosely adhering matter shall be removed by washing or flushing with water.

2.3 Care must be exercised to see that no portion of the automatic sprinklers is coated. The sprinklers may be protected by covering with a paper bag which must be removed immediately after the painting has been finished.

3. APPLICATION

3.1 Primer - apply "Porter #2100 Chromate primer - Red, 2 mils dry film thickness.

3.2 Finish - apply Porter #414 safety read 1½ mils dry film thickness.

0235406

TOWOLDMON0044004