FILE NAME: Hopeman Brothers (HB)

DATE: 1965

DOC#: HB033

DOCUMENT DESCRIPTION: Memo

Hopeman Brothers, Inc.

( ) of ( ) Sheets

TO: A. L. Peter FROM: M. Y. B. C. Hopeman

We are having problems with the dust created by sawing the Marinite panels - such dust is dangerous to the lungs.

I would like you to look into either a saw with a vacuum dust collector or some other method of preventing this dust.

Also, you might be able to find a saw blade which creates less dust due to its thickness or tooth edge.

B. C. H.

BCH:ah

DATE: 11/11/65 ANS: (Work Order No.) HULL L. NO.

DEFENDANT'S EXHIBIT tabbies HB01178

IPN10-53

PLAINTIFF'S EXHIBIT tabbies HB-49