6000 CFM 2100 Sq ft 1½" Tubes

PLAINTIFF'S EXHIBIT KM-193

Huland Brinkley, Director of Enforcement
Bay Area Air Pollution Control District
939 Ellis St.
San Francisco, Calif. 94109

KMX 02192

Dear Mr. Brinkley:

Please be advised that we use asbestos in the course of our operation, which may be consider an emission source under Regulation 8 - Emission Standards for Hazardous Pollutants.

We blend ingredients to produce products which contain from 0 to 6% Asbestos.

Our control for all dust is an Industrial Clean Air Series 700 Dust Collector. Pick up points are located at all dust emission locations and drawn by negative pressure to a central bag house. A 15 Hp blower produces 6000 CFM Vacuum. The Dust house contains 2100 Sq ft. of dacron 10 fiber. The dacron is not spun. The permeability is 2.857 CFM per square foot of material.

The system is monitored by a water gauge manometer.

Consumer Product Safety act
effects Joint Compounds but not Texture
January 16, 1978, the banned products cannot be manufactured or shipped from manufacturer facility
June 12, 1978, The banned products can not be sold or used, regardless of mfg date

~~O.S.H.A. of 1970~~
~~December 7, 1971 Temporary Std for Asbestos~~
~~July 7, 1972 Permanent Std~~
~~[ceiling limit of 10 Fibers/cc longer th]~~

Calif. Spraying law S.B. # 2419 Chapter 1432
Section # 25910
July 1, 1975, Not more than .5% in materials for spraying
July 1, 1976, NO Asbestos At All for spraying

KMX 02194

State of Calif. Dept. of Industrial Relations
Division of Industrial Safety.
Title 8.
Required reporting (registration & posting) and reporting to bargaining representative.
7/3/76 2 fibers/cc Max 10 fiber/cc

O.S.H.A of 1970

December 7, 1971 Temporary Std for Asbestos

July 7 1972 - Permanent Std

Ceiling limit of 10 Fibers per cc longer than 5 micrometers & 5 fibers/cc longer than 5 micrometers on a time-weighted average for an 8 hour shift.

July 1976 — 2 fibers/cc longer than 5 micrometers TWA

Caution labels

Medical Exams & records

J.

Senate Bill 1678 - Asbestos

Employer must report