PLAINTIFF'S EXHIBIT KBN-144

[redacted] ENGINEERS

INTEROFFICE MEMORANDUM

TO D.A. DeMario
AT Chicago

DATE July 1, 1981
FROM J.C. Schnepp
AT Chicago
JOB NO.

COPIES TO G. Gatcheff

SUBJECT HAZARDOUS AND NON-HAZARDOUS WASTE DISPOSAL FOR J & L COKE OVEN BATTERY PROJECT

We contacted Mr. Wayne Nichols, Director of the State of Ohio Environmental Protection Agency who referred us to his hazardous waste expert, Mr. Roger Hannahos. He described the rules, etc. and referred us to the North East District personnel, Ms. Debbie Berg and Ms. Malinda Becker. These persons were contacted with information as follows:

Asbestos materials are not considered hazardous and should be placed in 55 gal. steel drums and transported to the Doherty Land Fill in Geneva, Ohio (216) 466-4735. At present fifty 55 gal. steel drums is the total maximum daily delivery accepted at the land fill.

Sludge is handled as follows: A sample must be taken, sent for laboratory analysis, the results sent to the N.E. District of the O.E.P.A. If it is determined to be hazardous waste, then it must be sent to S.E.C.O.S. a secured land fill located in Clairmont County, near Cincinatti (513) 681-5731.

If it is determined to be non-hazardous waste, there are five (5) approved land fills in Ohio; the closest one to Youngstown is the Breitersteine Land Fill, Waynesburg, Ohio. In order for the non-hazardous waste to be accepted by the land fill, it must contain a minimum of 35% solids, no free standing water and must be approved by the N.E. District of the O.E.P.A.

The transporting of waste requires that the transporter secure an U.S.E.P.A. Identification Number. He must then register his trucks with the Ohio Public Utility Commission. The current charge is $25.00 fee plus $3.00 per truck. In the case of hazardous waste the generator should prepare the manifest.

The O.E.P.A. first holds the transporter responsible for the delivery of the waste and ultimately holds the generator responsible. In the case of a demolition contractor, he could be considered the transporter and generator, since it is not considered waste until it is discovered in a pipe and disturbed.

JCS:ja

[redacted]-51579

WLH	✓	SLM	
DE	✓	MJF	
CBT	✓	KW	
DE-Chi	✓	JG	
DDM	✓	MJS	
LDM		Purch.	✓
RCH			
RN			
PJZ		[redacted]SEN	
ZWISSLER	✓	FILE	✓ 01049
SPATH	✓		
HUNSACKER	2 LT		
		CD	

RECEIVED
1981
H. L. HUNSAKER

KEN 005743