




APH

oil boiler
water only



series 1B

APH-115
APH-150
APH-185



Cast iron repair parts for this boiler will be discontinued Dec. 1980.

13473

Repair part price for each part number is found at back of book.

cat. no.	description	part no.
3	section support & jacket stiffener	23774
4	canopy w/insulation	23776
5	flue baffle, 3 section	23683
6	flue baffle, 4 section	23775
7	combustion chamber bolts: 11 1/2"	5182
	14 1/2"	5183
	17 1/2"	5184
8	tie bolts: 7 3/4"	5099
	10 1/2"	5100
	13 3/4"	5095
9	1/2" drain flange	0601
10	1 1/2" return flange	2519
11	circulator gasket	6230
12	flange gasket	6232
13	sight opening cover	23784
14	air adjustment ring assembly	22482
15	draft tube sleeve insulation	6492
16	drain valve	5664
17	limit controls: AY-553R, high AY-552R - MILLIMETER (5833)	5802
18	limit control switch	7727
19	switch mounting plate for hi-lo switch	23295
20	limit control retainer bracket	23472
21	stream diverter	5950

* AY 552-R can be used for fine or millivoltage

(DRAFT TUBE AIR ADJ.
2. PRESSURE PLATE ASS'Y) - 22482


DRAFT TUBE SLEEVE ASS'Y - 23773

CANOPY GASKET

3/8" W X 1/16" THK X 5 3/4" LG. - 23681



3



4



5



6

7

8



9



10



11



12



13



14



15



16



17



18



19



20



21



22

APH oil boiler water only

note: parts are used for series 1B

cat. no.	description	part no.
22	combustion chamber assembly	9001
23	combustion chamber patch kit 8-250 (not shown)	6533

The APH section assemblies require strategic placement of blind nipples to insure proper internal circulation. For this reason individual sections are not available. Complete section assemblies must be ordered.

	<u>Top</u>	<u>CTR</u>	<u>BTM</u>	
* section assemblies including tie bolts:				
APH-115	4020	4021	4023	9268
APH-150	"	"	"	9269
APH-185	"	"	"	9270

* Boiler series number must be specified.

Repair part price for each part number is found at back of book.

117