PLAINTIFF'S EXHIBIT
KM-118

Paco Textures Corporation

1057 COMMERCIAL STREET • SAN CARLOS, CALIFORNIA 94070 • (415) 592-8128

January 13, 1976

Mr. Jon T. Marquardt
A Spray
4005 Deeble Street
Sacramento, California 95820

Dear Jon:

As stated in your letter of December 17, 1975 we have succeeded in making a ceiling texture without asbestos. However, we are also still making and selling the 6373C and 6374J Ceiling Texture that contain up to 0.5% asbestos. Both of which will be replaced or eliminated July 1, 1976. To be sure that you are getting the non-asbestos ceiling texture ask for the 6373E.

The preservative used in the 6373E, to prevent spoilage, is considered hazardous at full strenth. However, it is very diluted in the finished product.

Being a dry powder, the ceiling texture could create nuisance dust until it is mixed with water. Therefore, one should wear a protective respirator when ever visible dust occurs.

Also, it is always wise to use coveralls while working, clean hands and face throughly before eating and if a rash appears contact your doctor for possible allergy.

Sincerely,

Douglas W. Merrill

DWM/jlb

cc: Don Marquardt

67 235