→ Stan Shaw - St. Louis
R. P. Sullivan
Fluids File

October 6, 1967

Mr. L. V. Page
Lever Brothers Company
5300 Holabird Avenue
Baltimore, Maryland 21224

Dear Mr. Page:

Confirming my telephone call, the 18 drums Therminol FR-2 appear to be in good condition. Based on the analysis you have listed, if this material is still in your system, we would recommend running for another 30 days. Then, sample the material and send it to Mr. Stan Shaw at: Monsanto Co., 800 North Lindbergh Blvd., St. Louis, Missouri 63166. He will have the material tested to determine if satisfactory for continued use.

If the material has been removed from the system it can be reprocessed by sending it to:

Findett Service Co.
St. Charles, Missouri

It would be advisable to contact Mr. Milton Tegethoff, telephone RA 3-0240 (area code 314) for further information if necessary. As you know, Findett will be happy to test your samples before reclaiming, and advise estimate of cost.

If you have any further questions, please let me know,

Cordially yours,

C. R. Field
Office Manager

CRF/mjt

DSW 435073

STLCOPCB4088134