→MAY -0-81-E1536—1

EST. WGT. ~~7467~~ 6578 LBS.

| | |
|---|---|
| KM-7068-F (K) | BBK 8-29-77 |
| | DCG 8-30-77 |
| TYPED BY | |
| NSA 9-1-77 | |

MAKING NOTES

REMARKS

7956

Tot. Wgt. ~~8467~~# Req. ( )

NAME: MONASTRAL® RED B NON-BLEEDING

## INSTRUCTIONS -PRESSING- RECORD

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| VAT | | | | | | PRESSLOAD | 1ST | 2ND | 3RD | 4TH | 5TH |
| DATE | | | | | | STARTED | | | | | |
| TIME | | | | | | CAKES USED | | | | | |
| RELEASED BY | | | | | | WATER ON | | | | | |
| PRESS | | | | | | HRS. WASHED | | | | | |
| NO. OF CAKES | | | | | | OHMS | | | | | |
| PRESS | AGITATION | | | | | HRS. WASHED | | | | | |
| WASH TO | OHMS | | | | | OHMS | | | | | |
| TEST AFTER | HOURS | | | | | HRS. WASHED | | | | | |
| LOAD | | | | | | OHMS | | | | | |
| | | | | | | CAKE CONDITION | | | | | |
| | | | | | | NO. CARS LOADED | | | | | |
| | | | | | | EXPLAIN LOSSES | | | | | |
| SAMPLES | | | | | | | | | | | |
| DELIVER TO | | | | | | SAMPLED BY | | | RELEASED BY | | |

## -DRYING-

| | | | |
|---|---|---|---|
| HOURS | L.V. | H.V. | LUMP: - OK - WET - SALTS - CONTAMINAT |
| TEMP. | °F | °F | |
| | | | ADDITIONAL DRYING HOURS REQUIRED |
| SAMPLES | | | NO. CARS PULLED LUMP WGT. |
| DELIVER TO | | | SAMPLED BY RELEASED BY |

## -GRINDING-

| | | | | |
|---|---|---|---|---|
| MILL | SCREEN | RPM | SCREEN | RPM |
| MAX. TEMP. | °F | | MAX. TEMP. | °F |
| | | | EXPLAIN LOSSES | |
| SAMPLE AFTER / WITHOUT MIXING | | | DATE MIXED | |
| SAMPLES | | | | |
| DELIVER TO C T L | | | SAMPLED BY | RELEASED BY |

CG 16 CODE RW-768-P PKG. 01

MAX-0-81 E1536-2

EST. WGT. ~~7107~~ 6578 LBS.

Tot. Wgt. ~~8407~~ 7956# Req. ( )

PROCESSING INSTRUCTIONS: BATCH UNIT

| PROCESSES | APPROVED BY |
|---|---|
| RW-768-P (K) | BBK 8-29-77 |
| | DCG 8-30-77 |
| TYPED BY | |
| NSA 9-1-77 | |

MAKING NOTES

REMARKS

NAME: MONASTRAL® RED B NON-BLEEDING

## INSTRUCTIONS — PRESSING — RECORD

| | | | | | | | PRESSLOAD | 1ST | 2ND | 3RD | 4TH | 5TH |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| VAT | | | | | | | STARTED | | | | | |
| DATE | | | | | | | CAKES USED | | | | | |
| TIME | | | | | | | WATER ON | | | | | |
| RELEASED BY | | | | | | | HRS. WASHED | | | | | |
| PRESS | | | | | | | OHMS | | | | | |
| NO. OF CAKES | | | | | | | HRS. WASHED | | | | | |
| PRESS | | AGITATION | | | | | OHMS | | | | | |
| WASH TO | | OHMS | | | | | NRS. WASHED | | | | | |
| TEST AFTER | | HOURS | | | | | OHMS | | | | | |
| LOAD | | | | | | | CAKE CONDITION | | | | | |
| | | | | | | | NO. CARS LOADED | | | | | |
| | | | | | | | EXPLAIN LOSSES | | | | | |
| SAMPLES | | | | | | | | | | | | |
| DELIVER TO | | | | | | | SAMPLED BY | | RELEASED BY | | | |

## —DRYING—

| HOURS | L.V. | H.V. |
|---|---|---|
| TEMP. | °F | °F |

LUMP: — OK — WET — SALTS — CONTAMINAT

ADDITIONAL DRYING HOURS REQUIRED

SAMPLES

DELIVER TO

NO. CARS PULLED LUMP WGT.

SAMPLED BY RELEASED BY

## —GRINDING—

| MILL | SCREEN | RPM |
|---|---|---|
| MAX. TEMP. | °F | |

SCREEN RPM

MAX. TEMP. °F

EXPLAIN LOSSES

SAMPLE AFTER / WITHOUT MIXING

SAMPLES

DELIVER TO C T L

DATE MIXED

SAMPLED BY RELEASED BY

DUP050097040

MAKING INSTRUCTIONS: BATCH UNIT

ALM #2 C.V. 214,215,320 D.V. 321

CG 16 CODE RW-768-P PKG. 06 TIME ____ M

LOTMAY -0-81-E1536-1

| PROCESSES | | APPROVED BY |
|---|---|---|
| ( ) RW-768-P | (K) | BBK 8-29-77 |
| ( ) | ( ) | DCG 8-30-77 |
| ( ) | ( ) | |
| ( ) | ( ) | |
| TYPED BY NSA 9-2-77 | | |

TAB: PUNCH TOTAL WGT AS EST WGT 6548 ~~6578~~ ~~7397~~ LBS
EST WGT (DO NOT PUNCH)
(REQ # ____)

TAB: PUNCH FOLLOWING CONSUMPTIONS

TAB: DO NOT PUNCH

| CG | CODE | LOT | PQ | DISP | LBS | % | PULP WGT |
|---|---|---|---|---|---|---|---|
| 16 | RC-3-A | E12JJ | 93 | | 1339 | | |
| 16 | RC-3-A | | | | | | |
| 16 | RC-3-A | | | | | | |
| 16 | RW-768-P | E12602 | 93 | | 311 | | |
| 16 | RW-768-P | E13942 | 93 | | 12 | | |
| | | | | | | | |
| | | TOTAL WGT | | | ~~7956~~ 7917# | | |

7720/7917 X100 = 97.5%

(Reg. # 10738)

NON-BLEEDING

| MENT | | NAME: MONASTRAL® RED B | USE LBS. | N · CODE | ACCT LBS. |
|---|---|---|---|---|---|
| ISC 1 | | Note: Making Supv -- 1 hr before taking S 24 sample, advise CTL of status | | | |
| | 1 | Obtain as listed above | | RC-3-A | ~~1339~~ |
| | 2 | Calc for S 18 | 5399 | | 1339 |
| | 3 | ~~7932#~~ 5399# RC-3-A Pulp Wgt (S 1) = 1971 # water ~~7370#~~ | | | |
| LM 2 | 4 | Plug ALM # 2 outlet | | | |
| | 5 | Do not start agitator | | | |
| | 6 | Pump in RC-3-A from S 1 (Must be 18% Min) | | | |
| | 7 | Start Agitator | 330 | | 330 |
| | 8 | Add in 3-5 min | ~~200~~ | 741-B | ~~200~~ |
| | 9 | Stir 5 min & add Assume 50% | 4 | 7-D | 2 |
| | 10 | Rinse grating, sides & mixer basket with 200# water | | | |
| | 11 | Stir 20 min | | | |
| | 12 | Stop agitator | | | |
| | 13 | Record: pH 11.6 (10.0-12.0) | | | |
| | 14 | If necessary, adj to pH (10.0-12.0) Assume 50% | | 7-D | |
| | 15 | Record: pH Assume 75% | | 30-D | |
| | 16 | Pour in | ~~40~~ 42 | 195-B | ~~42~~ 42 |
| | 17 | Stir 5 min | | | |
| | | When scheduled, pour in Lot | | RW-768 | 39 |
| | | Note: Add as vol will permit During Homog | | | |
| V 3 | 17 | Run ALM thru Homog at 4800-5200 psi into V-320 | | | |
| | | Note: Return material homogenized below 4800 psi to ALM | | | |

MAY 26 1981

DUP050097041

V-320

| EQUIPMENT | | PAGE 2 CG 16 CODE RW-768-P (K) EST WGT. ____ LBS. | USE LBS. | N CODE |
|---|---|---|---|---|
| CV 3 (Con't) | 19 | Rinse ALM with 1971# water calculated in S 2 thru homog at 2000-5000 PSI | | |
| | 19 | Drain lines from homog to CV into drum & pour into CV | | |
| → | 20 | Stir 20 min | | |
| | 21 | Record: pH 11.2 (10.0-12.0) | | |
| | 22 | If necessary, adjust to pH 10.0-12.0 Assume 50% ____ | | 7-D |
| | | Record: pH ____ Assume 75% ____ | | 30-D |
| | 23 | Discharge ±25 G thru packout line & pour into CV | | |
| | 24 | Fill 1-16 ounce jar from packout line & deliver to CTL for color. Record in S 37 | | |
| | 25 | Fill 1-16 ounce jar from packout line & run 100 mesh screen test per SOP. Record results S 37 | | |
| | 26 | If screen test is OK, close manhole cover, turn off light, & leave agitator on. Note: If screen test is not OK, notify supervisor | | |
| Homog 4 | 27 | Clean Homog per SOP | 25 | 3-A |
| CV 5 | 28 | Add ____ # water as required to CV | | |
| | | Note: If test is satisfactory, omit S's 28-31 | | |
| | 29 | Start agitator & stir 20 min or longer to uniformity | | |
| | 30 | Fill 1-16 ounce jar from packout line & deliver to CTL for color. Record in S 37 | | |
| | 31 | Shut off agitator until test is available | | |
| | 32 | When test is satisfactory, start agitator | | |
| | 33 | Stir 5 min or longer | | |
| | 34 | Check packout scale accuracy: 50# ____ 500# ____ | | |
| | 35 | Discharge thru packout screen as follows: | | |

| PACKAGE N-CODE | | SCHEDULED PACK | TOTAL NET PACK |
|---|---|---|---|
| N-1775 | 55 | 4 ea | 1800 |
| N-[illegible] | | ± 10 | 20 |
| N-1701 | KKS | ± 77 ± 120 | 118 3900 |
| | | GRAND TOTAL NET PACK | |

Note: After discharging ±25 G, fill 2-16 ounce jars from packout line, mark "FINAL." Deliver to CTL when packout is completed. Record in S 37

36 Stop agitator

37 Record:

| | Results | Time | Supv |
|---|---|---|---|
| S 25 Screen test | ✓ | | |
| S 24 Color Sample to CTL | ✓ | | |
| S 30 Resample to CTL | ✓ | | |
| S 35 Sample during packout | ✓ | 2:15 PM | |
| S 35 Deliver to CTL | | | |

| START | FINISH | OPTR |
|---|---|---|
| 7:00 AM | 3:00 PM | 322 |
| 11hr | 7hr | 116 |

DUP050097042

5/4/78

DATE: 5/22/81

TO: AREA SUPERVISOR

DISPERSED PASTE - 24 HOUR SHEET

1ST SHIFT

OPERATOR: #322 M. NELSON

| Batch Code | "N" Code | Lot Number | 100% Weight | No. of Drums | Comments |
|---|---|---|---|---|---|
| RW-768 E-1536 | RC-3-N | E-1255 | | 12 | |

Status at shift change

HOMD. To 320 VAT

OPERATOR:

2ND SHIFT

| Batch Code | "N" Code | Lot Number | 100% Weight | No. of Drums | Comments |
|---|---|---|---|---|---|
| | | | | | |

Status at shift change

DUP050097043

450
x4
1800

32
x3
96
22
118 Kits
Shipped

118
50
000
5900
5920

DUP050097044