

MCC
MCC 950920

Monsanto

FROM: NAME & LOCATION)

J.J. McClellan O-10, Texas City

DATE	April 28, 1981	cc:	Tony Ozarchuk	O-22
			M.A. Riddle	O-22
SUBJECT	MINUTES OF HOURLY SAFETY COMMITTEE		PMSB	
	MEETING HELD MARCH 31, 1981		SHAC	
REFERENCE			V.P. Osburn	AB

TO :

W.E. Bean	SS-4
J.M. Burkhalter	SS-10
Jessie Butler	51D
L.E. Derrick	AB
Austin Gates	LD
Vivian Hargrove	35P
A.E. Mofley	15/16D
R.L. Sartain	SS-12

OLD BUSINESSManlifts

No report on job safety analysis to date.

Impact Wrenches used by Ships

This will be discussed with Material Handling at the next meeting.

NEW BUSINESSDriving in Plant

Excessive speed continues to be a problem. Fred Herzog reports that this problem is recognized and should improve.

Drinking Water--Milky Color

The milky color is only due to excess air and is not a problem according to the Utilities Department.

Bicycles and Trackmobile

*RR Track
crossing at
Main St. & W. A-
Signs - Joe
Hogan has
ordered signs*

Bicycles crossing tracks by the P.E. hopper car wash station constitute a hazard when the trackmobile is pushing several cars. This has been investigated by several people and the general agreement is that it is a hazard. Ways to correct this problem will be discussed at the next meeting.

AN Barge Loading

Rate of loading is reported to be causing seals to be blown on the barge pump. This will be discussed with Material Handling at the next meeting.

SC

13015

Joe McClellan
J.J. McClellan

LAM014232

br