



PLAINTIFF'S EXHIBIT

FD-1663

Mr. E.H.T.

Inter Office

Personnel and Organization Staff

April 14, 1981

Mr. R. P. Doherty
Manufacturing Manager
Sheldon Road Plant

D.D. BAKER

cc W. G. McGruther

Subject: Airborne Asbestos Monitoring - Sheldon Road Plant

The attached report describing an industrial hygiene study at the Sheldon Road Plant contains recommendations for control of employee exposure to asbestos dust. Implementation of these, or equally effective, control methods is essential to:

- . Assure conservation of employee health
- . Adhere to Company directives regarding occupational health issues
- . Comply with OSHA regulations and standards
- . Meet UAW contractual agreements regarding employee health and safety.

Study recommendations are summarized as follows:

1. Remove residual asbestos in the supply air ducts of the former mix room and clean room fixtures, walls and ceilings of settled asbestos-containing dust.
2. Comply with OSHA regulations relative to warning signs, respiratory equipment, special clothing, and medical monitoring during removal of asbestos from the supply air ducts and cleaning of the former mix room.
3. Seal entrances to the asbestos silos and post asbestos hazard warning signs on the silos.
4. Dispose of asbestos now remaining in silos as soon as practicable.

Your response to me by May 14, 1981 with a plan including a timetable to implement these recommendations will be appreciated.

Paul E. Toth

Paul E. Toth, Manager
Industrial Hygiene & Toxicology Department
Employee Health Services

jk
Attachment

8006 1827

PQ

SCF-FORD-3092

PRODUCED BY FORD