

FILE NAME: Chrysler (CHRY)

DATE: 1983-1987

DOC#: CHRY094

DOCUMENT DESCRIPTION: Asbestos Warning Label

Asbestos Warning Label 1983 - 1987

CAUTION

THIS PRODUCT CONTAINS ASBESTOS.
AVOID CREATING DUST. BREATHING
ASBESTOS MAY RESULT IN SERIOUS
BODILY HARM.

Asbestos Warning Label 1987 - Present

DANGER

CONTAINS ASBESTOS FIBERS
AVOID CREATING DUST
CANCER AND LUNG DISEASE
HAZARD



Inter Company Correspondence

Phone No.

Date

File Code

May 5, 1983

To-Name & Department

Division

Plant/Office

CIMS Number

R. L. Anderson
from-Name & Department

Materials Planning

Service &

Parts Oper.

Center Line

423-09-0

Division

Plant/Office

CIMS Number

D. N. James

Industrial Hygiene

Industrial
RelationsChrysler
Center

417-05-1

Subject:

ASBESTOS WARNING LABELS FOR MOPAR PRODUCTS

file

MAY 9 1983

The majority of occupational health professionals concede that the existing body of scientific evidence addressing human exposure to asbestos indicates that long term exposure to asbestos fibers of a specific size range and in sufficient concentration will result in an increased risk of respiratory fibrosis. Additionally these data indicate that asbestos exposure in concert with other environmental exposures, and in particular cigarette smoking, significantly increases the risk of respiratory cancer.

The existing public sensitivity to issues of environmental hazards dictates that the Corporation exercise prudent management and recognize its responsibility to the aftermarket consumers of Mopar products by providing appropriate warning labels on asbestos containing products. Labeling should be restricted to those products which have the potential of creating an asbestos dust hazard such as brake linings, clutch facings, transmission bands and heat resistant gaskets or seals. It is the recommendation of this department that the asbestos products identified above bear the following legend:

CAUTION

This product contains asbestos
Avoid creating Dust
Breathing asbestos dust may
result in serious bodily harm

The technical resources of this department are available to assist you in this area.

D. N. James
D. N. James
Industrial Hygiene Specialist

hm

cc: M. W. Grice
J. L. Koblin
N. McCallum
G. A. Sattelmeier

RECEIVED
NOV 11 1983

Date 11/1/83

Name & Department

Division

Plant/Office

CIMS Number

L. J. O'Brien - Litigation and Insurance of THE GENERAL COUNSEL
CHRYSLER CORPORATION Division Highland Park 417-27-40
CIMS Number

L. Anderson - Materials Planning S&PO Center Line 423-11-03

ASBESTOS WARNING LABELS FOR MOPAR PRODUCTS

Service and Parts Operations has taken the following actions to implement your recommendations regarding asbestos warnings:

1. Part numbers in the high risk categories of brake components, clutch facings, transmission bands, and heat resistant gaskets and seals have been inspected for asbestos content. At present, 301 part numbers have been identified as containing asbestos. A small number of part numbers have yet to be inspected due to no stock being available. It is expected that these will be completed by the end of December 1983. Our Package Engineering department is in the process of adding warning label requirements to the packaging specifications for parts confirmed as containing asbestos. All new receipts of material for asbestos containing parts are to have warning labels on their packages. A plan is being developed to label all existing inventory of asbestos containing parts in our depots across the country. It is estimated that this will be completed by the end of January 1984. Labels for asbestos parts bear the following legend:

Caution
This product contains asbestos.
Avoid creating dust.
Breathing asbestos may result
in serious bodily harm.

A copy of the label is attached.

2. Service manuals, according to our Service Publications department, for 1984 domestic passenger car and truck models contain asbestos warnings in the brake and clutch sections. Asbestos warnings for the import service manuals are on the agenda for discussion with Mitsubishi Motors during a November 1983 visit by Chrysler to Japan. Copies of the warnings in the domestic service manuals are attached.

If you have any questions or require additional information regarding asbestos warnings on Chrysler Service and Parts products, please contact me.

R. L. Anderson
R. L. ANDERSON

RLA:pj
Attach.

cc: R. J. Dolan
J. L. Freeman
T. M. Govern

L. B. Richey
G. A. Sattemeier
F. W. Vertin
-

DC 03621

CAUTION

THIS PRODUCT CONTAINS ASBESTOS.
AVOID CREATING DUST. BREATHING
ASBESTOS MAY RESULT IN SERIOUS
BODILY HARM.