TO BE FILED
MARINE DEPARTMENT
P___T (6 mo.)___

EXXON GETTYSBURG #5 - 4 YEAR SPECIAL SURVEY
NEW PORT NEWS SHIPYARD - 1978
ITEM BY ITEM

1	As Written	NC
2	As Written	NC
3	As Written	3,730
4	As Written - See Attached Report, Sample Sent 6/3/78 - Reported OK - 6/23/78	398
5	As Written - Note (1) haul - (5) Lay Days	39,047 550
6	As Written	3,460
7	Delete 10,000 - substitute 2,300. Add Muck 10 Center Note - Norfolk ship removed 8,000 bbls slop. Six (6) hour delay. Broken barge line alongside 1730 - 6/2 - start 1935 - finished 1200 - 6/3/78 NPN start 1400 hrs. - 6/3 - finished 1800 - 6/3/78	6,300
8	As Written - No Charge	NC
9	As Written	8,046
10	As Written	8,000
11	As Written	900
12	As Written	13,724
13	As Written	6,049
14	As Written	9,000
15	As Written - Note only one (1) Non Restricted Phone	550
16	As Written - Add total of nine (9) stockings. Unstop one drain @ midship aft portside.	450 2,125
17	As Written	950
18	As Written	350
19	As Written	7,875
20	As Written - Except delete 200 sq. ft., substitute 150 sq. ft. Add Blasted four (4) anodes only.	6,675
21	As Written	3,500
21A	As Written	1,148
21B	As Written	413
21C	As Written	-700
22	As Written	1,525
23	As Written	1,615
23A	As Written	310
24	As Written	1,515
24A	As Written - Add Renew 8" glass General Alarm - Operating Platform	290
25	As Written	8,885
26	As Written Note - $1200 Repairs - $2400 Betterments	R-1200 B-2400
27	Delete - "Designated Port & Stbd wing tanks of Vessel" - Substitute "Pump into slop cars"	3,920
28	As Written - Repaired in shop	2,700
28A	As Written	5,400
29	As Written	2,318
29A	As Written	373
29B	As Written - Except cancel Reference To Packing Glands	8,501

29C	As Written	2,953
29D	As Written	2,935
30	As Written	4,188
		150
30A	As Written	1200
31	Cancel	7,570
31A	As Written	
32	As Written - Delete - "Remove inspection plates for examination of pintle nut and bushing and taking of bushing clearance." Delete - "Reinstall inspection plate and pintle nut retainer stops."	3,050
32A	As Written	250
		150
33	As Written	3,565
34	As Written	3,476
34A	As Written - Add "Furnish and apply Belzona to 3 ft. x 1 ft. area"	330
		150
35		260
36	Delete paragraphs 3-4-5 and 6	2500
36A	As Written	10,701
36B	As Written	3,658
36C	As Written	6,800
37	As Written - Add - Took audio gauge readings on Fwd Port cofferdam	35,400
		250
37A	As Written - Add - Mucked engine room cofferdam	4,697
37B	As Written	1,420
38	As Written	4,800
39	As Written	6,500
39A	As Written	480
39B	As Written	1,500
39C	As Written	950
39D	As Written	325
40	As Written	19,630
40A	As Written	430
40B	As Written	510
40C	As Written	1,347
40D	As Written - Add - Renew missing thermometer on LP Turbine oil line	1,925
40E	As Written	300
41	As Written	3,025
42	As Written	750
43	As Written	1,500
44	As Written	1,380
45	As Written - Except cancel last paragraph	3,292
45A	As Written	178,892
45B	As Written	2,657
45C	As Written	2,800
45D	As Written	3,228
46	As Written	2,610
47	As Written	1,500
48	As Written	4,615
49	As Written - Except as indicated	8,078
49A	As Written	1,040
49B	As Written	320

49C	As Written	250
50	As Written	3,400
51	As Written	13,845
51A	As Written	2,060
51B	As Written	420
51C	Covered in 51A	-
51D	As Written	2,060
51E	As Written	515
52	As Written	4,425
52A		460
52B	Cancel first paragraph	755
53	Betterment - As Written	17,100
53A	As Written - Add - "Relocate Mast Guywires"	650
53B	Betterment - As Written	16,360
54	As Written	10,790
54A	As Written	10,790
54B	As Written	450
54C	As Written	6,652
54D	As Written	1,580
54E	As Written	375
54F	As Written	980
55	Cancel	
		1,500
56	As Written - Vendor met lab.	5,500
57	As Written	8,755
57A	As Written	4,400
57B	As Written	870
58	As Written	1,650
59	As Written	27,100
60	As Written	2,600
61	As Written	6,370
61A	As Written	930
62	As Written	9,227
62A	As Written	3,045
62B	As Written	610
62C	As Written	3,234
62D	As Written	1,016
62E	As Written	647
62F	As Written	2,400
62G	As Written	70
63	As Written	1,382
64	As Written	24,300
64A	As Written	1,424
65	As Written - Cancel paragraph "D"	28,300
65A	As Written	110
65B	As Written	(12,000)
		200
		1,520
		500
		900
65C	As Written	2,240
65D	As Written	220
65E		150
66	As Written	4,635

67	As Written		260
68	As Written		2,200
			(1,100)
69	As Written		120
69A	As Written		220
70	As Written		2,400
			2,000
			320
71	As Written		3,400
71A	As Written		250
71B	As Written		366
72	As Written		5,250
73	As Written		4,200
74	As Written		1,575
75	As Written		1,000
76	As Written		3,630
77	As Written	- Note - Only two (2) Valves sent to Henzie	1,600
78	As Written		9,500
79	As Written		11,500
79A	As Written		1,680
80	As Written		28,296
81	As Written		1,535
82	As Written		450
83	As Written		51,418
83A	As Written		18,840
84	As Written		2,800
84A	As Written		322
85	As Written		1,400
86	As Written		150
87	As Written		2,400
88	As Written		2,535
89	As Written		375
90	As Written		1,350
91	As Written		275
92	As Written		563
92A	As Written		1,035
93	As Written	- Add - Repair operating valve assembly. Replace missing and broken gauges on #10#e feed pumps.	1,377
94	As Written		1,080
95	As Written		1,020
95A	As Written		523
96	As Written		828
97	As Written		350
98	Cancelled		NC
99	As Written		950
99A	As Written		3,800
100	As Written		1,380
101	As Written		1,380
101A	As Written		2,150
101B	As Written		930
101C	As Written		2,680
101D	As Written		304
101E	As Written		5,308
101F	As Written		665

102	Cancel	NC
103	As Written	19,900
103A	As Written	3,340
103B	As Written	276
104	As Written	450
104A	As Written	600
105	As Written	2,400
105A	As Written - Add - Renewed gland stubs on drain cooler outlet valves	1,250
106	As Written - Cancel third paragraph	6,200 (6,200)
106A	Add - 80' x 1/4" x 2 1/2" - (2) 32 sq. ft. - 1.4" Diamond Tread Plate	4,000
107	As Written	342
108	As Written	452
109	As Written	8,680
109A	As Written	366
110	Cancel first paragraph	2,134
111	Cancel	NC
112	As Written	1,946
113	As Written	1,200
114	As Written	770
114A	As Written	454
114B	As Written	555
114C	As Written	1,336
115	As Written	3,203
116	As Written	385
116A	As Written	220
117	As Written	7,250
118	As Written	1,640
119	As Written	950
120	As Written	1,950
121	As Written	3,847
122	As Written	1,882
123	As Written	3,240
124	As Written	3,900
125	As Written	3,253
126	As Written	2,400
127	As Written	2,400
127A	As Written - Add - Repair hangers on gauge lines under platform. Renew defective coil on evap feed pump motor control.	675 3,600 1,950
128	As Written	7,500 650 250 600
128A	As Written	1,920
128B	As Written	996
128C	As Written	300
129	As Written	1,214
130	Cancel	NC
131	As Written	1,343

132	As Written	1,440
132A	As Written	825
132B	As Written	787
133	Cancel	NC
134	As Written	125
135	As Written	5,325
136	As Written	8,176
137	As Written	110
138	Cancel	NC
139	As Written	4,066
140	As Written	5,190
140A	As Written	2,706
141	As Written	1,600
141A	As Written	950
142	As Written	1,450
143	As Written	2,484
144	As Written	850
145	As Written	3,851
146	As Written	452
147	As Written	706
147A	As Written	308
148	as Written	677
149	As Written	1,512
150	As Written	2,418
151	As Written	298
152	As Written	1,260
152A	As Written	1,260
153	As Written	980
154	As Written	1,054
		6,000
155	As Written	300
		3,000
155A	As Written	2,500
156	As Written	728
157	As Written	1,635
157A	As Written	550
158	As Written	996
159	As Written	544
160	As Written	3,528
160A	As Written	1,800
161	Cancel	NC
162	As Written	596
162A	As Written	2,170
163	As Written	2,100
164	As Written	5,360
165	As Written	6,850
166	As Written	4,260
167	As Written	3,240
168	Cancel	NC
169	As Written	1,673
170	As Written	1,394
171	As Written	1,460
172	As Written - Except delete Renewal of Expansion Joint	1,070
172A	As Written	(910)

172B	As Written	320
173	As Written	4,000
		720
173B	As Written	480
174	As Written	1,245
175	As Written	720
175A	As Written	5,743
176	As Written	3,696
177	As Written	138
178	As Written	3,293
		4,206
		320
179	As Written	320
180	As Written	25
181	As Written	1,770
		640
182	As Written	90
183	As Written	520
184	Cancel	NC
185	As Written	635
185A	As Written	125
186	As Written	250
187	Cancel "A" - "B" - As Written	4,590
		735
188	As Written	1,932
		1,932
188A	As Written	3,693
188B	As Written	382
		1,004
188C	As Written	330
		1,150
189	As Written	3,550
190	As Written	485
191	As Written	8,035
192	As Written	6,025
193	As Written	271
193A	As Written	618
193B	As Written	492
194	As Written	1,050
194A	As Written	50
194B	As Written	110
195	As Written	2,157
195A	As Written	1,060
196	As Written	602
197	As Written	615
197A	As Written	220
198	As Written	350
199	As Written	832
		800
200	As Written	350
201	As Written	100
202	As Written	2,910
203	As Written	NC
203A	As Written	1,611

204	As Written	420
205	As Written	640
206	As Written	575
207	As Written	920
208	As Written	450
209	As Written	450
210	As Written	125
211	As Written	1,080
212	As Written	157
213	As Written	1,253
214	As Written	2,033
215	As Written	6,100
		132
215A	As Written	(4,505)
215B	As Written	3,908
215C	As Written	337
216	As Written	8,711
216A	As Written	581
		1,200
		600
216B	As Written	650
216C	As Written	6,150
216D	As Written	451
217	As Written	2,400
218	As Written	3,040
218A	As Written	297
219	Cancel	NC
220	As Written	300
221		7,977
221A		1,135
222	Cancel	NC
223	As Written	2,720
224	As Written	326
224A	As Written	4,800
225	As Written	450
226	As Written	523,340
226A-B-C-D - Cov		Cov
227	Cancel	NC
228	As Written	Cov
228A	As Written	16,867
228B	As Written	71
229	Cancel	NC
230	As Written	539
230A	As Written	539
230B	As Written	1,437
231	As Written	586
232	As Written	544
233	As Written	3,000
234	As Written	371
		(1,351)
235	Cancel - covered in item #62	NC
236	As Written	550
236A	As Written	190
236B	As Written	5,465

237	Cancel	NC
238		4,270
		(1,000)
238A		700
239	As Written	1,218
240	Cancel	NC
241	See - 241A	44,185
		550
241B	As Written	650
242	Cancel	NC
243	Cancel	NC
244	As Written	3,492
244A	As Written	1,178
244B	As Written	149
245	Cancel	
246	As Written	2,264
247	As Written - Owners Acct	NC
248	As Written	18,895
248A	As Written	532
248B	As Written	2,708
248E	As Written	664
249	Cancel	NC
250	Cancel	NC
251	As Written	12,607
252	Cancel	NC
253	Cancel	NC
254	As Written	566
255	Cancel	NC
256	As Written	11,593
257	As Written	4,760
257A	As Written	1,200
257B	As Written	3,712
258	As Written	150,000
258A-B-C-D-E-F - As Written		Cov
259	As Written - Delete paragraph #3	99,603
259A	As Written	5,465
259B	As Written	590
259C	As Written	330
259D	As Written	920
259E	As Written	2,640
259F	As Written	4,128
259G	As Written	900
260	As Written	216,440
260A	As Written	Cov
260B	As Written	Cov
260C	As Written	Cov
260D	As Written	Cov
260E	As Written	Cov
261	As Written	1,625
261A	As Written	2,550
261B	As Written	Cov
261C	As Written	750
262	Cancel	NC
263	Cancel	NC

264	As Written	1,665
265	As Written - Except delete 1-3-4-5-6-7-11-12-13	6,353
265A	As Written	Cov
266	As Written	2,824
266A	As Written	539
267	See 267A	Cov
267A	As Written	2,067
268	Cancel	NC
269	As Written	4,575
270	As Written - Also freed up 14 chocks, installed doublers under new chocks. Each 30" x 3 ft. x 5/8" modified hand rails to suit new chocks.	4,244
271	Cancel	NC
272	Cancel	NC
273	As Written	27,754
273A	As Written	1,024
273B	As Written	1,365
274	Cancel	NC
275	Cancel	NC
276	As Written	5,230
276A	As Written	5,230
276B	As Written	1,150
277	As Written	900
278	As Written	3,300
278A	As Written	281
279	As Written	1,422
279A	As Written	2,400
		120
280	As Written	4,831
281	As Written	891
282	As Written	301
283	Cancel	NC
284	As Written	460
285	As Written	360
285A	As Written	3,191
286	Cancel	NC
287	As Written	1,176
287A	As Written	198
287B	As Written	358
288	As Written Betterment	24,347
288A	As Written	Cov
289	Cancel	NC
290	As Written	304
291	Cancell	NC
292	As Written	44,347
293	As Written	1,000
		671
293A	As Written	125
294	As Written Betterment	5,120
294A	As Written	1,250
295	As Written	460
296	As Written Betterment	13,555
296A	As Written	920
296B	As Written	1,250

297	As Written	1,250
297A	As Written	650
298	As Written	212
299	As Written	936
299A	As Written	1,142
299B	As Written	1,151
299C	As Written	360
300	As Written	3,260
300B	As Written	365
300C	As Written	357
301	As Written	NC
301A	As Written	1,568
301B	As Written	760
302	As Written	616
303	As Written	240
303A	As Written	240
304	As Written	295
304A	As Written	154
305	As Written	1,200
306	As Written	NC
		1,500
306A	As Written	600
307	As Written	145
307A	As Written	1,800
308	As Written	2,119
309	As Written	522
310	As Written	594
311	As Written	374
312	As Written	2,673
312A	As Written	1,834
313	As Written	589
313A	As Written	488
313B	As Written	303
314	As Written	79
314A	As Written	297
315	As Written	145
316	As Written	320
317	Cancel	NC
318	As Written	722
319	As Written	226
320	As Written	75
321	As Written	77
322	Cancel	NC
323	As Written	NC
323A	As Written	NC
324	As indicated - covered in other items	NC
325	As Written	NC
326	As Written	NC
327	As indicated - covered in other items	NC
328	As Written	968
329	As Written	434
330	As Written	2,378