FILE NAME: AMMCO (AMC)

DATE: 1978 May 3

DOC#: AMC007

DOCUMENT DESCRIPTION: Letter from NLCSC to AMMCO re Liability Study

NATLSCO
National Loss Control Service Corporation

Long Grove, IL 60049 • 312 | 540-2400
TWX 910 | 651-3571

a subsidiary of
KEMPER CORPORATION

May 3, 1978

Mr. Robert S. Hampton, Jr.
Product Engineering Manager
Ammco Tools, Inc.
2100 Commonwealth Avenue
North Chicago, IL 60064

RE: PROPOSED PRODUCT SAFETY STUDY FOR MODELS 800, 880 and 890 BRAKE SHOE GRINDERS

Dear Mr. Hampton:

This letter will confirm our recent telephone conversation.

We propose to conduct a product liability study for the Models 800, 890 and 880 brake shoe grinders. This study will focus upon the following areas:

1. Engineering - The engineering design aspects of the machine will be examined, including the type of consideration given to operator error, misuse, or abuse of the equipment. The type of design testing which has been conducted will also be reviewed.

2. Quality Control - The quality control system as it relates to these three pieces of equipment will also be reviewed. This will include the type of incoming inspection or testing done on purchased parts, finished product testing and inspection, as well as the documentation and recordkeeping aspects of the quality control function.

3. A review of printed literature and information on the products will also be conducted. This includes warning and precautionary labels on the products themselves, sales catalogs, and operating instructions.

The study will result in a written report to Ammco, containing all our analyses of the present product liability exposures of the equipment and recommendations on how these exposures can be controlled.

(L)

NATLSCO
National Loss Control Service Corporation

As I indicated, this service is normally provided at a cost of $300/day. We have anticipated that this should take no more than one day at your facilities in North Chicago, Illinois to gather the appropriate information, and approximately three days of report preparation. The total charges for this service will not exceed $1200.

We will need your written authorization prior to initiation of the study. Should you have any questions regarding the above, please feel free to contact me.

Sincerely,

E. L. Ziemba
Manager, Product Safety Services
Direct Dial Number: 312/540-2016

ELZ/jbc