

J-M Manufacturing Co., Inc.**Internal Correspondence**

To : C. G. Stelchek, Denison
From : E. E. Wang
Copies : T. E. Lohman, J.T. Armstrong, Denison
Subject : INDUSTRIAL HYGIENE SURVEY

Date: August 1, 1986



A comprehensive industrial hygiene survey for your plant will be conducted next month. The various airborne contaminants to be sampled/analyzed this time will be the same as those of last year (i.e., asbestos, respirable silica, VCM, organic vapors, CO, nuisance dust, and noise). The total sampling time for each airborne contaminant is around four hours. The total number of samples to be taken and the details are given below:

<u>Airborne Contaminant</u>	<u>Total Number of Samples to be Taken</u>
Asbestos	41
Respirable Silica	16
VCM	10
Organic Vapors	23
CO	3
Nuisance Dust	1
Noise	47

Due to the change in plant operating conditions, however, you may have some new established stations that need to be sampled. If this is the case, exchange those old sampling stations having good track records for the new established stations, so that the total sampling number can be maintained at the same.

To avoid unnecessary resampling caused by poor ventilation, and/or improper work practice, check carefully your ventilation systems/work practices before the scheduled sampling date. Make certain that all ventilation systems are in good operating condition and established work practices are followed. This is particularly important when the new PEL for asbestos exposure has been lowered to 0.2f/cc.

E. E. Wang

AUG. 04 1986

D 001823