

NAVY SERVICE PLAN

REPORT NO. 56

JANUARY 1, 1954 TO FEBRUARY 28, 1954

E. HAIG

SERVICE ENGINEERING SECTION

GENERAL ELECTRIC COMPANY

SCHENECTADY, N.Y.

28. SHIP'S INDEXKEY TO SYMBOLS UNDER "UNIT"

T - Propulsion Turbine
 EG - Propulsion Generator
 M - Propulsion Motor
 G - Main Reduction Gear
 t - Ship's Service Generator Turbine
 eg - Ship's Service Generator
 g - Ship's Service Generator Reduction Gear
 m - Auxiliary Motor
 CTD - Control Device
 at - Auxiliary Turbine

<u>SHIP'S NAME</u>	<u>TYPE & NO.</u>	<u>PARA.</u>	<u>RECENT RPTS.</u>	<u>UNIT</u>	<u>REPORTED</u>
<u>CRUISERS</u>					
BALTIMORE	CA-68	1	55	t-CTD	Faulty reg.
<u>AMPHIBIOUS VESSELS</u>					
ALGOL	AKA-54	2	54	t	Excess vibration.
LEO	AKA-60	3		T	Worn packing.
WANTUCK	APD-125	4		T-EG	Wiped bearing.
<u>ESCORT VESSELS</u>					
CROSS	DE-448	5		G	Required inspection.
<u>AUXILIARY VESSELS</u>					
BALD EAGLE	AF-50	6		t	Wiped bearing.
GOLDEN EAGLE	AF-52	7		T-G	Required repairs.
SUAMICO	AO-49	8		T-t-g	Required repairs.
MARIAS	AO-57	9		at	Required repairs.
SCHUYLKILL	AO-76	10	55	EG-M	Required inspection.
ANACOSTIA	AO-94	11		EG-M-eg-CTD	Required repairs.

SHIP'S INDEX (CONT'D)

<u>SHIP'S NAME</u>	<u>TYPE & NO.</u>	<u>PARA.</u>	<u>RECENT RPTS.</u>	<u>UNIT</u>	<u>REPORTED</u>
<u>AUXILIARY VESSELS (CONT'D)</u>					
MISSION CAPISTRANO	AO-112	12		T-t-at	Required repairs.
MISSION CARMEL	AO-113	13	55	t	Faulty governor.
MISSION SAN DIEGO	AO-121	14	53	T-t-g	Required repairs.
MISSION SANTA BARBARA	AO-131	15		t-g-at	Required repairs.
WACISSA	AOG-59	16		EG-M	Required repairs.
GEN. HUGH J. GAFFEY	AP-121	17		T	Required repairs.
GEN. NELSON M. WALKER	AP-125	18	51,53,54	T-EG-M- t-eg- CTD	Required repairs.
GEN. MAURICE ROSE	AP-126	19	55	M	Required repairs.
GEN. H. F. HODGES	AP-144	20		t	Required repairs.
GEN. J. H. McRAE	AP-149	21		CTD	Required adjustment.
DAVID C. SHANKS	AP-180	22	51	t	Required repairs.
FRED C. AINSWORTH	AP-181	23	51,53,54	t-eg	Required repairs.
GEORGE W. GOETHALS	AP-182	24	54	CTD	Faulty breakers.
SGT. CHARLES E. MOWER	AP-186	25	55	t	Required repairs.
UPSHUR	AP-198	26	52,55	G-eg	Required repairs.
JASON	ARH-1	27		t	Required repairs.