

CAUTION: Contains asbestos fibers. Avoid creating dust. Breathing asbestos dust may cause serious bodily harm.

When servicing this brake lining or any component related to it or located near it, prevent asbestos dust from becoming airborne by vacuuming the assembly with an industrial type vacuum cleaner equipped with a high efficiency filter system and by washing the assembly with an appropriate brake parts washer if necessary. Never remove dust or dirt from this assembly by blowing with compressed air.

L1510

FAFD1 1796