WORK REQUEST

TO

APPLIED SCIENCES
RESEARCH CENTER LABORATORIES
MONSANTO INDUSTRIAL CHEMICALS CO.

WORK REQUESTED

GLC - MASS SPEC

REASON/COMMENTS

SANTOTRAC 50 FROM
FAILED HEYNAU DRIVE

SAMPLE IDENTIFICATION

MONSANTO 50
HEYNAU SANT. 50
SAMPLE

DSW 297910

R. A. LUEBKE
REQUESTER

BLDG. T LAB./OFFICE 303

MAIL ZONE T3F

PHONE NUMBER 4901

PRODUCT SANTOTRAC 50

BUSINESS GROUP FUNCTIONAL PRODUC

DATE SUBMITTED 4-18-77

DATE NEEDED BY ASAP

JOB NUMBER 45-000-760.40-1413135

SAMPLE DISPOSAL ☒ RETURN
☐ DISCARD

R-108 REV. 7-72

(SUBMIT WHITE, YELLOW AND GREEN COPIES)

STLCOPCB4067821

REPORT SHEET

GC/MS Analyses of the new fluid and that from the failed Heyman drive showed there were no significant differences in the chromatographic patterns. Based on this result no detailed MS interpretation was carried out. This result does not exclude possible alterations in components which do not chromatograph.

DSW 297911

3

GC/MS - 77-59

SIGNATURE	DATE	NOTE BOOK
Robert G. Colby, II	4/19/77	

STLCOPCB4067822