March 3, 1970

Mr. Kenneth R. Carlson
Repair Sales
Repair Division, Westinghouse Electric Corp.
1500 W. Cornell Street
Milwaukee 9, Wisconsin

Dear Mr. Carlson:

Your request for cleaning Inerteen off the floor was forwarded to me for reply. The best cleaning is a strong laundry detergent and warm water. Solvents such as trichloroethylene are also excellent when used with old rags to remove deposits of Inerteen.

Unfortunately, if you are concerned with a plastic floor covering such as vinyl tile, the Inerteen is an excellent plasticiser which attacks the surface. In these cases the only solution is replacement of the contaminated floor covering.

We trust this answers your request. If we can be of further service, please advise.

Regards,

J. G. (Jim) Bryant
Product Specialist
Dielectric Fluids

/dn
cc: C. L. Curtis - St. Louis
P. G. Dunigan - St. Louis
G. Randall Graham - New York

PLAINTIFF'S EXHIBIT 1633

NEV 004937

704175

STLCOPCB4023705