NAME OF RECEIVING TSD FACILITY: U W Treatment Co. EPA I.D. NUMBER: G A D 1 1 1 1 0 0 0 0 0 **FORM C**

FROM WHOM RECEIVED: NAME: Dirty Dons Chemicals EPA I.D. NUMBER: X Y Z 0 0 0 0 0 1 1 1 1

HAZARDOUS WASTE RECEIVED FROM OFF-SITE HANDLERS AND ITS DISPOSITION

1. EPA Hazardous Waste Number	E001 / U080	D001 / F003 / U002 / F005	U154 / U220	D007	
2. Description of Waste	Compound Paint Remover-Corrosive Material	Acetone, Toluene & Methyl Alcohol		Chrome Trivalent Paint undercoat.	TOTAL IN TONS
3. On Hand, On-Site on Jan. 1, 1985	360.277			700.360	1060.637
4. Received During 1985	17566.934	20900.500			38467.434
5. TOTAL Amount for Which to Account	17927.211	20900.500		700.360	39528.071
6. Reshipped to:ID# X Y Z 0 0 0 0 0 0 0 0 0 Name: A B C Corporation	17000.000				17000.000
7. Reshipped to:ID# X Y Z 1 2 3 4 5 6 7 8 9 Name: Waste-a-Way Co.		10000.000			10000.000
8. Reshipped to:ID# _____ Name:					
9. Reshipped to:ID# _____ Name:					
10. Treated On-site	927.211				927.211
11. Treatment Code	T01				
12 Disposed of On-site		10000.000			10000.000
13. Disposal Code		D80			
14. On Hand, On-Site on Dec. 31, 1985		900.500		700.360	1600.860
15. Storage Code		S01		S02	
16. Other (Explain on Line 17)					
17. Explanation of Line 16					
18. TOTAL Amount of Disposition	17927.211	20900.500		700.360	39528.071

EXAMPLE

Comments:

Page ___ of ___

SC1 03069