

FILE NAME: Kaiser Gypsum (KG)

DATE: 1972 June 20

DOC#: KG111

DOCUMENT DESCRIPTION: Raw Material Specifications - Drywall Accessory
Products - Asbestos

RAW MATERIAL PALLIUM
 DRYWALL ACCESSORY
 PRODUCTS

ASBESTOS
 7RF10

LETIN NO: RM-J043
 DATE: 6/20/72
 PAGE: 1 of 1

APPROVALS:

CANCELS: RM-J045
 DATE: 12/4/69

USES:

Joint and Finish Compounds, Texture Paints

APPROVED SOURCE:

Philip Carey

ALTERNATE SOURCE *:

Johns-Manville

SPECIFICATIONS:

- | | |
|---|--|
| 1. Mixing Water Requirement | 480 to 550 |
| 2. Free moisture (200°F) | 2.0% |
| 3. Color | Light Gray |
| 4. Grit | 0.05% maximum. All
passing 80 mesh screen |
| 5. Calcium carbonate (CO ₂ method) | 1.0% maximum |
| 6. Canadian screen | 0.0-0.0-0.0-16.0 |
| 7. pH (10% dispersion) | 7-8 |
| 8. Wet bulking | 250-350 |

PLAINTIFF
 EXHIBIT

HOBBS
 11-4-9

The following information is for Kaiser Gypsum Company personnel only:

Testing Schedule: Take a minimum of one 1/2 pound sample from each pallet in shipment, with a maximum of 20 samples. Test two random samples for grit and wet bulking. Test 10 samples for mixing water requirements. Retain a representative sample from each shipment for one year.

SAFETY: Employees should wear respirators when handling, weighing and batching asbest

- * Use Alternate Source in emergency only due to color. For regular use, Alternate Source must be rechecked by Research and "approved."

PLTF 0216

RAW MATERIAL BUYER
 DRYWALL ACCESSORY
 PRODUCTS

ASBESTOS
 7RF9

LETIN NO: R/A-J046
 DATE: 6/20/72
 PAGE: 1 of 1

APPROVALS:

CANCELS: RM-J046
 DATE: 12/9/69

USES:

Joint and Finish Compounds, Texture Paints

APPROVED SOURCE:

Philip Carey

ALTERNATE SOURCE *:

Johns-Manville

SPECIFICATIONS:

1. Mixing Water Requirement 450 to 550
2. Free moisture (200°F) 2.0%
3. Color Light Gray
4. Grit 0.05% maximum. All passing 80 mesh screen
5. Calcium carbonate (CO₂ method) 1.0% maximum
6. Canadian screen 0.0-0.0-0.0-16.0
7. pH (10% dispersion) 7-8
8. Wet bulking 200-300

The following information is for Kaiser Gypsum Company personnel only:

Testing Schedule: Take a minimum of one 1/2 pound sample from each pallet in shipment, with a maximum of 20 samples. Test two random samples for grit and wet bulking. Test 10 samples for mixing water requirements. Retain a representative sample from each shipment for one year.

SAFETY: Employees should wear respirators when handling, weighing and batching asbestos.

- * Use Alternate Source in emergency only due to color. For regular use, Alternate Source must be rechecked by Research and "approved."

PLTF.0217

RAW MATERIAL & RESIN
DRYWALL ACCESSORY
PRODUCTS

ASBESTOS
SG 210

BULLETIN NO: RMJ-047
DATE: 6/20/72
PAGE: 1 of 1

APPROVALS:

CANCELS: RMJ-20
DATE: 9/13/69

APPROVED SOURCES:

Union Carbide
(SG-210)

SPECIFICATIONS:

- | | |
|-------------------------------------|--------------|
| 1. Magnetite (%) | 2.5 maximum |
| 2. Reflectance, G. E. Photovolt (%) | 68.0 minimum |
| 3. Dry Bulk Density, lbs/cu.ft. | 5-6 |
| 4. Wet Screen, Retain on | |
| 80 mesh (%) | 0.8 maximum |
| 325 mesh | 15.0 maximum |

WARNING

Employees should wear respirators when handling, weighing and batching asbestos.

RAW MATERIAL BULLETIN IN
DRYWALL ACCESSORY
PRODUCTS

ASBESTOS
7TF1

BULLETIN NO: RM-J050
DATE: 6/20/72
PAGE: 1 of 1

APPROVALS:

CANCELS: RM-J050
DATE: 1/26/71

USES:

Joint and Finish Compounds, Texture Paints

APPROVED SOURCE:

Philip Carey

ALTERNATE SOURCE *:

Johns-Manville

SPECIFICATIONS:

1. Mixing Water Requirement 330 to 370
2. Free moisture (200°F) 2.0% maximum
3. Color Light Gray
4. Grit 0.05% maximum. All passing 80 mesh screen
5. Calcium carbonate (CO₂ method) 1.0% maximum
6. Canadian screen 0.0-0.0-0.0-16.0
7. pH (10% dispersion) 7.5-8.5
8. Wet bulking 100-130

The following information is for Kaiser Gypsum Company personnel only:

Testing Schedule: Take a minimum of one 1/2 pound sample from each pallet in shipment, with a maximum of 20 samples. Test two random samples for grit and wet bulking. Test 10 samples for mixing water requirements. Retain a representative sample from each shipment for one year.

SAFETY: Employees should wear respirators when handling, weighing and batching asbestos

- * Use Alternate Source in emergency only due to color. For regular use, Alternate Source must be rechecked by Research and "approved."

PLTF 0219