

VCM SURVEY REPAIR LIST

LOCATION	TYPE	DESCRIPTION	CONCENTRATION	REPAIR STATUS
NM	V(L)	Manway into the New Module FVCM Receiver	100 ppm	Complete
NM	F(G)	At RX-743 on top of the Condenser on the North side next to Bleeder Valve 590	50 ppm	Complete
NM	F(G)	At RX-743 on top of the east side Condenser Recovery Line Flange between Valve and Condenser	120 ppm	Complete
NM	F(L)	Under Blowdown Tank on top of South Filter upstream of the New Module Blowdown Tank	75 ppm	Complete
OM	F(L)	East of Pressure Gauge 145 on the top vertical Flange connected to the vent on top of the South Batch Water Stripper	100-150 ppm	Complete
OM	F(L)	North of the VCM Condenser in the Old Module on the valve on top of the West Header	500 ppm	Complete
OM	F(G)	At RX-400 on the Flanged top	500 ppm	Complete
OM	V/F(G)	On the Vent Line leaking from the bottom the Flange below the Pressure Relief Valve, between the 3" Tufline Valve with the 3" Flange	100-200 ppm	Complete
TF	V(L)	The upper most valve above the pump at the north VCM pump at the Tankfarm	800 ppm	Complete

F - Flange L - Liquid Service
V - Valve G - Gas Service