

Distribution

F
2.4


To:
From: K. W. Birck
Date: October 28, 1985
Subject: VCM LEAK SURVEY

Interoffice
Communication

VISTA

Attached are the results of the completed 1985 Comprehensive VCM Leak Survey. A total of thirty-seven (37) leaks were found and repaired. Every flange, connection, valve, etc. on the attached isometric drawings was checked with a portable hydrocarbon detector (HNU). Those points with readings above 50 ppm with the probe close to the equipment as possible were considered leaks and were noted. A tabulated list of all leaks over 50 ppm VCM is attached.

If there are any questions or comments, please advise.


K. W. Birck
Process Engineer


F. G. Jeanson
Process Engineer

8P

attachments

c: JF, JWW, DWH, CWT, RAF, CRS, AHS, VEM, VLT