

FILE NAME: Allied Signal Bendix (ASB)

DATE: 1966

DOC#: ASB067

DOCUMENT DESCRIPTION: PA Dept of Health Field Activity Report

REGION V DEPARTMENT OF HEALTH & OCCUPATIONAL HEALTH EMPLOYEES COUNTY
 PROD. MFG. OR SERVICE Electronics MALE 100 67
 DATE 9/21/66 FIELD ACTIVITY REPORT FEMALE 185 IND. CODE
 PLANT Bendix Corporation TOTAL 285 36

ADDRESS Lincoln Highway East, York

PERSON INTERVIEWED Frank Schroeder TITLE Maintenance Foreman
 PURPOSE: INVEST.; SURVEY; INSPECT.; PRELIM.; F.U.; CONF.; VISIT; Lewis Nawro, Superintendent of
 REASON: SELF-INIT.; O.D. REP.; COMPL.; REQUEST; SOURCE Manufacturing

SPECIFIC HAZARD OR CONDITION	WORKERS EXPOSED	RECOMMENDATIONS	ACCOMPLISHED		
		WRITTEN - VERBAL	YES	NO	IN PROG.
Fibrous glass dust	3	None pending laboratory analysis of samples submitted for reweighing.			

SAMPLES COLLECTED work atmosphere (5) TOTAL 5
 (NO. & KIND)
 DETERM. MADE _____ TOTAL _____
 (NO. & KIND)
 MEDICAL _____ O.D. REPORTED, NO. & KIND _____

REMARKS Premeighed membrane filters submitted for analysis of fibrous glass. This is a resurvey
(8 points)
conducted to obtain a larger sample for analysis. by F. Miller

PUNCH CARD ☒ YES ☐ NO ☒ YES ☐ NO