KEMPER INSURANCE

CABLE ADDRESS KEMPERACO

MUTUAL INSURANCE BUILDING - CHICAGO 10

LOngbeach 1-8000



April 4, 1966

Mr. W. Leeder, Safety Director
Victor Manufacturing & Gasket Company
5750 West Roosevelt Road
Chicago, Illinois 60650

Dear Mr. Leeder:

The attached industrial hygiene report covers the results of the study made in your plant on March 18, 1966.

Investigated at that time were the asbestos operation and the rubber sheeting mills.

The results of the study showed excessive concentrations of asbestos dust at the bagging and beater operations. Also, excessively high concentrations of toluene were found at the sheeting mill #2707.

My thanks are extended for the courtesy and consideration shown on this visit. Should you have any questions as to the report or the recommendations made, please do not hesitate to contact me.

Yours very truly

George J. Krafcisin

G. J. Krafcisin
Industrial Hygienist
Special Technical Services Section

788-7-466
Enc.