ABERDEEN CHEMICAL PLANT—DOSIMETRY RECORD

№ A 0638

Name Doug Spann Shift A (D) Date 11/9/81

Social Security No. 418-66-3073 Job Code 84C0

	Start	Stop
Instrument No. 625	Time 7:00 AM(X) PM( )	7:00 AM( ) PM(X)
Noise Cell No.	Airflow	

	HAZARD	SAMPLE CONCENTRATION (Time Weighted Average)	
✓	VCM	3.1 – PPM	Air Vol. (Liters)
	Lead	–Micrograms/M^3	PEL: –Micrograms/M^3
	Antimony	–Micrograms/M^3	
	Total Dust	–Micrograms/M^3	
	Noise	–% PEL	115 dBA? Yes / No
			Analyst J Grace
			Analysis Date 11-18-81

Hazard: VCM (✓) Lead ( ) Antimony ( ) Dust ( ) Noise ( ) _____ ( ) № A 0638

1. I came to work at 7 AM (✓) PM ( )
2. I left work at 7 AM ( ) PM (✓)

Firewatch Work? Yes / No (Circle One)

3. I did the regular work of a (enter Job Class) Chief Lead
4. I used a respirator during the following jobs (check one)

	None	Dust Mask	Air-Line Resp.	Scott Air-Pak	3 M Air Hat
			✓		

5. The following unusual events may have caused me to be overexposed:

Isolating VC Chg Pumps & Lic Compressors

6. Other comments and information (Use reverse side of card)

Signature Douglas Spann

Please complete and return to Guard

CONOCO CHEMICALS – ABERDEEN PVC PLANT NOTICE OF MONITORING RESULT

№ A 0142

To: Doug Spann Date: 11/20/81

From: Ginny Bell, R.N.

Subject: VCM (✓) Lead ( ) Noise ( ) _____ ( )

1. You are hereby notified that on 11/9/81 your exposure to the subject hazard was as shown below:

Hazard		TWA Exposure
VCM	PEL: 1 PPM	3.1 PPM
Noise	Over ( ) Under ( ) 115 dBA	% of PEL
Lead (Micrograms)	TOT: PEL: Per M^3	Per M^3

2. This exposure was above (✓) below ( ) the permissable exposure limit.
3. The corrective measures being taken to reduce exposures to this hazard to safe limits are contained within the company's written plan. This plan is made available for your inspection in the Safety Department at all times and you are encouraged to review it.
4. Please sign and return this notice.

Employee Signature Doug Spann